

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 31037

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0219/2020/NS
Date	:	29-Feb-20

Vehicle IN workshop. Please arrange for survey.

Your insured veh no : SLA 4695 X

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Hitachi Capital Asia Pacific Pte Ltd
Address	:	7 Bright Hill Drive #11-03 Singapore 579599
Telephone	:	(HP) +65 96302524
Type of Claim	:	Third Party Claims
Policy No.	:	G 300061599 MCY
Vehicle No	:	SKW 6568 M
Model Code	:	Q7 3.0 TFSI QU
Model / Year	:	30/9/2015
Engine No	:	CRE 047618
Chassis No	:	WAUZZZ4M8GD008099
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	27-Feb-20
Place of Accident	:	Moulmein Road U-turn

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKW 6568 M

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assv and front parking aid.	S/N \$	480.00	✓
2	To dismantle and renew front bumper and lhs front fender. Re-organise front crash management components. Reinstall all parts removed.	\$	2,400.00	1000
3	To respray front bumper, lower spoiler, lhs front fender and wheel arch trims. ⁶⁰⁰ 550 ⁶⁰⁰	\$	3,000.00	1500
4	To dismantle lhs front suspension assy. Inspect for damages and renew accordingly. ³⁰⁰	S/N \$	2,400.00	?
5	To renew lhs front rim. Carry out wheel alignment.	S/N \$	280.00	✓
6	To carry out diagnostic check.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	<u>\$ 8,752.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKW 6568 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>X Repair.</i>	\$ 2,449.00	
2	FRONT BUMPER FIXING PARTS <i>X</i>	\$ 420.00	
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>X } NN</i>	\$ 41.00	
4	FRONT FENDER - LH <i>/ BNC</i>	\$ 1,525.00	
5	FRONT FENDER ATTACHMENT PARTS <i>X NN</i>	\$ 72.00	
6	FRONT FENDER BRACE - LH <i>?</i>	\$ 96.00	
7	S-LINE INSCRIPTION <i>/ AC.</i>	2 \$ 233.00	
8	WHEEL HOUSING LINER <i>?</i>	\$ 226.00	
9	WHEEL HOUSING LINER ATTACHMENT PARTS <i>?</i>	\$ 52.00	
10	REAR WHEEL HOUSING LINER - LH <i>X NN</i>	\$ 256.00	
11	FRONT WHEEL COVER - LH / RH <i>/ AC.</i>	2 \$ 1,080.00	
12	FRONT ALUMINIUM RIM - LH <i>/ AT.</i>	\$ 1,542.00	
13	FRONT WISHBONE LINK <i>?</i>	\$ 388.00	
14	SUSPENSION GUIDE <i>?</i>	\$ 972.00	
15	GUIDE - LH UPPER FRONT / REAR <i>?</i>	\$ 610.00	
16	WHEEL BEARING HOUSING - LH <i>?</i>	\$ 733.00	
17	SWIVEL JOINT <i>?</i>	\$ 208.00	
18	WHEEL HUB <i>?</i>	\$ 460.00	
19	DOUBLE ANGLED BALL BEARING <i>?</i>	\$ 237.00	
20	TIE ROD END <i>?</i>	\$ 190.00	
21	TYRE <i>X NN</i>	TBC	
22	SUNDRIES <i>?</i>	\$ 400.00	

TOTAL SPARE PARTS	: \$ 12,190.00
TOTAL LABOUR CHARGES	: \$ 8,752.00
GRAND TOTAL	: <u>\$ 20,942.00</u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Surveyed Date

:

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

5 & Days.

Guro Q. A. L.

before paint photos.

03/3/2020

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant