

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20003425/KTF3E2

Date: 31/03/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00005742000
Claimant Vehicle No : FL4004D **Insured Vehicle No :** YN5983K
Date of Loss: 21/02/2020 Nature of Claim: TP Claim No: SNM20D201077C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FL4004D**
Make & Model: HONDA FS150F, 149cc Engine No: KC27E2213704
Reg. Date: 23/01/2019 (Man. Year: 2018) Chassis No: PMKKC27A0KB204854
Colour: Multi-colour Odometer: 29398 km
Engine Capacity: 149 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 90/80R17 Rear Tyre Size: 120/70R17
Front Left Side: IRC 4 mm Rear Left Side: Michelin 6 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 22/03/2021
Date Inspected: 03/03/2020 Inspected At: Heng Yap Seng Auto Services
160 Sin Ming Auto City, #08-13
Singapore 575722
Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

NOTE: PENDING ESTIMATE IN MERIMEN

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 31 Mar 2022)	
Parts:	N/A	HONDA FS150F 149cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FL4004D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >