

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

siak tong@lioncityrentals.com.sg

Ms AIG Asia Pacific Insurance Pte Ltd

Date 2/3/2020

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLR274P
CHASSIS NO : GP71046221
MAKE / MODEL : Honda Shuttle 1.5 Hybrid
DATE OF ACCIDENT : 29/02/2020
YOUR INSURED VEHICLE NUMBER : GBC2904P
MILEAGE : 225952 Km

<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>	
1 Rear tailgate	1PC	\$ 1,850.00	\$ 1,850.00	bt / 1250
2 Rear tailgate windscreen moulding	1PC	\$ 195.00	\$ 195.00	ac /
3 Rear tailgate windscreen glass	1PC	\$ 2,850.00	\$ 2,850.00	bt / 1210.30
4 Rear back door Honda emblem	1PC	\$ 81.30	\$ 81.30	ac /
5 Rear back door VEZEL emblem	1PC	\$ 86.80	\$ 86.80	ac /
6 Rear tailgate HYBRID emblem	1PC	\$ 86.00	\$ 86.00	ac /
7 Rear tailgate lock	1PC	\$ 380.00	\$ 380.00	bt / 200
8 Rear tailgate door lock catch	1PC	\$ 120.00	\$ 120.00	bt /
9 Rear tailgate weatherstrip	1PC	\$ 280.00	\$ 280.00	ac / 168.50
10 Rear tailgate rear inner trim cover	1PC	\$ 500.00	\$ 500.00	de / 320
11 Rear tailgate licence lamps	1PC	\$ 120.00	\$ 120.00	x nn
12 Rear tailgate chrome garnish	1PC	\$ 550.00	\$ 550.00	ac / 383.60
13 Rear wiper motor assy	1PC	\$ 600.00	\$ 600.00	x nn
14 Rear wiper blade	1PC	\$ 30.00	\$ 30.00	ac /
15 Rear wiper arm	1PC	\$ 130.00	\$ 130.00	ac /
16 Rear bumper	1PC	\$ 1,680.00	\$ 1,680.00	de / 1150
17 Rear bumper lower skirt	1PC	\$ 550.00	\$ 550.00	x nn
18 Rear bumper RH reflector	1PC	\$ 132.80	\$ 132.80	x nn
19 Rear bumper LH reflector	1PC	\$ 132.80	\$ 132.80	x nn
20 Rear end panel	1PC	\$ 830.00	\$ 830.00	bt / 658.80
21 Rear end panel top garnish	1PC	\$ 155.00	\$ 155.00	de /
22 Rear spare tyre panel	1PC	\$ 1,200.00	\$ 1,200.00	de /
23 Rear spare toolkit compartment box	1PC	\$ 550.00	\$ 550.00	de / 420
24 R/L tail lamp	1PC	\$ 850.00	\$ 850.00	ac / 690.60
25 R/L tail gate reflector	1PC	\$ 720.00	\$ 720.00	ac / 390
26 R/R taillamp	1PC	\$ 850.00	\$ 850.00	ac / 690.60
27 R/R tail gate reflector	1PC	\$ 720.00	\$ 720.00	ac / 308
28 Rear smart buzzer	1PC	\$ 180.00	\$ 180.00	x nn
LIST TOTAL S\$:			\$ 16,409.70	
20% DISCOUNT S\$:			\$ 3,281.94	
			\$ 13,127.76	8724 6479.20

SPECIAL NETT

- 1 Bumper and end panel clips
- 2 Reverse sensor
- 3 Body sealant
- 4 Windscreen sealant
- 5 Rear number plate
- 6 DECAL

1 SET	\$	200.00	40w	—
1 SET	\$	260.00	200nw	✓
1PC	\$	300.00	60w	✓
1PC	\$	100.00	60	✓ nec
1PC	\$	50.00	end	✓ 45.
1PC	\$	20.00	net	✓
Special Nett Total S\$:		\$	930.00	

425

LABOUR CHARGES

- 1 To labour charge for removing rear back door, rear end panel, spare tyre panel, rear bumper to facilitate repairs and replacement of damaged parts \$ 1,750.00 1200
- 2 To respray rear bumper, rear back door, spare tyre panel and end panel \$ 1,400.00 1000
- 3 Transfer door mechanism to facilitate repairs and replacement of parts \$ 120.00 60
- 4 To remove & install rear windscreen glass \$ 180.00 120
- 5 To conduct a standard of operating procedures post repairs scan test as a requirements upon completion of collision repairs \$ 300.00 150
- 6 To deactivate and activate high voltage hybrid battery as a safety precautions \$ 300.00 150 ✓ plus
- 7 To provide transport for DECAL at VICOM \$ 100.00 60

LABOUR TOTAL S\$: \$ 4,150.00 2740.
 TOTAL S\$: \$ 18,207.76
 7% GST \$ 1,274.54
 GRAND TOTAL S\$: \$ 19,482.30

6979.20
 425
 2740
 10144
 1/5 \$ 8100 *
 7 days

Tanflin 97495749
 'wp'
 2/3/20 @ 5:15pm
 7 days

Tanflin @ Iliantown
 Lumpsun
 Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey and/or after spray painting
- To display a sign indicating resurvey
- To stop work until the resurvey is complete
- To stop work until the resurvey is complete
- To stop work until the resurvey is complete
- To stop work until the resurvey is complete
- To stop work until the resurvey is complete

Acknowledged by Repairer
 Signature: _____
 Date: _____