



**ACE AUTOLUTION PTE LTD**

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

TP111  
Xiao Tony

PU11319417

Vehicle No. SMM8334L HONDA VEZEL

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR ADJUSTMENT
	<b>PARTS (LIST ITEMS)</b>			
1	FRONT BUMPER <i>beh</i>		815.00	✓
1	FRONT BUMPER REINFORCEMENT <i>Beit.</i>		<del>570.00</del>	321
1	FRONT BUMPER REINFORCEMENT GARNISH <i>new</i>		170.00	+
1	FRONT BUMPER SIDE RETAINER RH <i>new</i>		108.00	+
1	FRONT BUMPER CHROME <i>new</i>		325.00	+
1	FRONT BUMPER TOW COVER <i>new</i>		56.80	+
1	FRONT BUMPER FOG LAMP RH <i>new</i>		341.20	+
1	FRONT BUMPER FOG LAMP BRACKET RH <i>new</i>		69.60	+
1	FRONT GRILLE <i>could.</i>		<del>428.00</del>	383.
1	FRONT GRILLE OUTER CHROME <i>could</i>		412.60	✓
1	FRONT GRILLE OUTER CENTRE LOGO <i>new</i>		58.00	—
1	FRONT HEADLAMP LH <i>could.</i>		1827.80	✓
1	FRONT HEADLAMP BRACKET LH <i>could</i>		65.00	—
1	FRONT BONNET <i>new</i>		1350.00	+
1	Front Grille Logo <i>45 new</i>		6597.00	
1	Air Con Condensate Side Guide <i>55 new</i>		1319.40	20%
		less	5277.60	
	<b>SPECIAL NETT ITEMS</b>			
1	FRONT GRILLE CLIPS <i>new</i>		<del>80.00</del>	30
1	FRONT HEADLAMP CLIPS <i>new</i>		80.00	+
1	FRONT BUMPER CLIPS <i>new</i>		<del>50.00</del>	30
	<b>Total Parts</b>		5487.60	



**ACE AUTOLUTION PTE LTD**  
 13 Kaki Bukit Road 4 Bartley Biz Centre #03-29  
 Singapore 417807  
 Tel:6702 4282 Fax:6702 4202

Vehicle No. SMM8334L HONDA VEZEL

S/N	DESCRIPTION	REPAIRER'S ESTIMATE	OUR ASSESSMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1200.00	400.
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1000.00	300
3	To remove and refix wiring at damaged areas	150.00	30.
4	To perform anti rust treatment on affected areas	120.00	X
5	To remove and replace front headlamp 730	120.00	X
	Labour Total :	2590.00	
	TOTAL (PARTS & LABOUR) :	8077.60	

Adrian L  
 L/S 10/03/20

03 Days.

total 3988.24  
 L/S: 3.2K

3.2K

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: