

## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705 FAX Number : 63685592 Estimator Yelephone Number : 68662823 Accident Reporting Number : 68662672

Date Generated: 13/03/2020 : PohSuan User ID

	Section A - Accident Details
Registration Number	SHB5185L
Case Reference Number	TAX/02/20/2093
Registration Date	1/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	MOHAMED RAMZAN BIN MOHD DALI
Type of Accident	Head to Rear
Accident Date and Time	28/2/2020 2:35 PM
Accident Reported Date and Time	29/2/2020 9:09 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24105961
Special Instruction to ARC,if any	TP
Prepared Date and Time	29/2/2020 11:15 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Summary of Repair Estimates	5	
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$300.00
Total Spray Cost	\$1,458.00	\$400.00
Total Spare Part Cost	\$4,676.67	\$1,340.20
Total Other Cost	\$360,00	\$80.00
TOTAL COST	\$7,001.67	\$2,120.20 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	Taufikh (LKK) / AIG
ARC / Surveyor Sign Off Date	05/03/2020 9:24 AM	05/03/2020 11:20 AM
Signature	2	
Remarks	Total number of repair days = 3 days. SUP = 0 day.	Resurvey before paint



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated: 13/03/2020 User ID : PohSuan

	Section C - Quota	tion and Accident Invoice Details	
Quotation Number	QN-2003-0165	Invoice Number	
Quotation Date	11.03.2020	Invoice Date	
Invoice Amount		Prepared Date	

ALL LOSS PROPERTIES AND ACTION AND ACTION AND ACTION AND ACTION AND ACTION ACTION AND ACTION	Section D - Details of Repair Estimates	No. of the last of
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if
TO REPAIR REAR PORTION	\$507.00	applicable \$300.00
Total Labour	\$507.00	\$300.00

Job Scope	Quotation from ARC	Adjusted by Surveyor, if
TO RESPRAY REAR BUMPER	\$378.00	applicable \$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$0.00
O RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$1,458.00	\$400.00

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20,00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$360.00	\$80.00

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price	Estimator Approved	Surveyor Approved
		52591470 50	SEAL, RR BUMPER , RH	0.00	\$85.20	0.00	\$0.00	Replace	Check X
		52592470 40	SEAL, RR BUMPER, LH	0.00	\$85.20	0.00	\$0.00	Replace	Check X
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace
		52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace /
		52565479 00	FILLER, RR BUMPER , RH	0.00	\$119.90	0.00	\$0.00	Replace	Check
		52566479 00	FILLER, RR BUMPER, LH	0.00	\$119.90	0.00	\$0.00	Replace	Check X
		52169470 20	COVER, GUARD RR BUMPER LOWER	0.00	\$14.80	0.00	\$0.00	Replace	Check
		76801471 10A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$891.20	100.00	\$0.00	Replace	Repair R
		75403480 10	EMBLEM SUB-ASSY REAR	1.00	\$46.30	25.00	\$34.73	Replace	Replace
		75441470 90	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace
			NAME PLATE (PRIUS) . LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace



Total

## SMRT Accident Vehicle Repair Estimates

REINFORCEMENT

SMRT Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705 FAX Number : 63685592

Estimator Telephone Number: 68662623 Accident Reporting Number: 68662672

Date Generated : 13/03/2020 User ID : PohSuan

52462470 PAD, RR BUMPER, RH & 0.0	0.00	\$3.80	0.00	\$0.00	Replace	Check X	
52462470 PAD, RR BUMPER, RH & 0.0	0.00	\$3.80	0.00	\$0.00	Replace	Check X	\ X
10 LH , 3 52191470 SEAL, RR BUMPER ARM, 0.0 30 RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Check X	> nn
52599680 STOPPER, RR BUMPER, 0.0 30 RH & LH	0.00	\$4.30	0.00	\$0.00	Replace	Check X	
40 RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given	
52576470   RETAINER, RR BUMPER,   0.0			10.00	\$0.00	Replace	Not Given V	
The state of the s	0.00	\$111.50		12011 1111	Replace	INOL GIVER V	

318.80

1340.20 + 300.00 + 480.00 + 2120.20\*\* 3,20%

239.10

Fruit + Poh Sun & 212020, Bolys