

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

CAR IN



GST REG. NO : M2 - 0020081 - X

03 MAR 2020

## E S T I M A T E

Estimate No. : <b>b1 54641</b>	Page No. : <b>1 of 5</b>
Date Estimated : <b>02/03/2020</b>	
Prepared By : <b>Shukhaizi Bin Misbah</b>	

<b>- ESTIMATE REPAIR FOR -</b> Loh Choon Yan APT BLK 138B Lorong 1A Toa Payoh #28-22  Singapore 312138	<b>- ACCOUNT - 121</b> AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Chartis Building Singapore 079120
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFK8833G	WBATR92000LE25897	22/10/2018	X3 xDrive30i	0

DESCRIPTION	VALUE
Replace front bumper including attachment, front right fender <sup>850</sup> front right wheel arch, front right door	2550 4,275.00
Painting front bumper, front right side panel, front right wheel arch, front right door, front right door cover. <sup>150</sup>	3406 3,406.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
To replace wheel rim including balancing. (1x).	94.00
To carry out body cavity preservation. (Per panel-2x).	236.00
sundries	150.00
Total Labour 1:	<b>8,338.00</b>

DESCRIPTION	QTY	PRIC	VALUE
Disk wheel, <sup>CAT</sup>	1	1,457.45	1,457.45
FRT RH DOOR <sup>00</sup>	1	1,538.20	1,538.20
FRT RH SIDE PANEL <sup>00</sup>	1	848.45	848.45
FRT RH 1 SIDE PANEL BRACKET	1	35.10	35.10
RH BOTTOM SIDE PANEL BRACKET	1	35.10	35.10
FRT RH 2 SIDE PANEL BRACKET	1	35.10	35.10
FRT RH 3 SIDE PANEL BRACKET	1	35.10	35.10
FRT RH FOG LAMP SUPPORT <sup>x</sup>	1	65.00	65.00
FRT BUMPER PANEL PRIMED (M/CAM) <sup>x R</sup>	1	1,679.10	1,679.10
SET MOUNTING PDC/PMA SENSOR FRT (M) <sup>?</sup>	1	135.05	135.05
FRT RH DOOR PROT. STRIP PRIMED (M) <sup>x R</sup>	1	151.20	151.20
FRT RH SIDE PANEL FINISHER (M) <sup>CAT</sup>	1	81.05	81.05
FRT RH WHEEL ARCH TRIM PRIMED (M) <sup>CAT</sup>	1	281.35	281.35
RH SILL TRIM PRIMED (M LIGHT) <sup>x</sup>	1	424.40	424.40
FRT LH WHEEL ARCH TRIM (M) <sup>x</sup>	1	234.45	234.45

303, Alexandra Road  
 Sime Darby Performance Centre  
 Singapore 159941  
 Fax. 64747770

280, Kampong Arang Road  
 East Coast Centre  
 Singapore 438180  
 Fax. 63449773

315, Alexandra Road  
 Sime Darby Business Centre  
 Singapore 159944  
 Fax. 64796601 (AfterSales)  
 64796624 (Motorrad)

**GST REG. NO : M2 - 0020081 - X**

**E S T I M A T E**

Estimate No. : <b>b1 54641</b>	Page No. : <b>2 of 5</b>
Date Estimated : <b>02/03/2020</b>	
Prepared By : <b>Shukhaizi Bin Misbah</b>	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SFK8833G</b>	<b>WBATR92000LE25897</b>	<b>22/10/2018</b>	<b>X3 xDrive30i</b>	<b>0</b>

<p><i>Steve (LKK) W/L P/L</i>  <i>83228813 3/3/20, 4.00pm</i>  <i>6 days</i>  <i>P/P</i>  <i>By BOL SLJ</i></p>	<p>Total Parts : <b>7,036.10</b></p>
---	--------------------------------------

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

	<table style="width:100%"> <tr> <td style="width:70%">Labour 1</td> <td style="width:10%">:</td> <td style="width:20%; text-align: right;"><b>8,338.00</b></td> </tr> <tr> <td>Parts</td> <td>:</td> <td style="text-align: right;"><b>7,036.10</b></td> </tr> <tr> <td>Labour 2</td> <td>:</td> <td style="text-align: right;"><b>0.00</b></td> </tr> <tr> <td>Excess</td> <td>:</td> <td style="text-align: right;"><b>0.00</b></td> </tr> <tr> <td>Total GST @ 7%</td> <td>:</td> <td style="text-align: right;"><b>1,076.19</b></td> </tr> <tr> <td><b>Grand Total</b></td> <td style="border-top: 1px solid black;">:</td> <td style="text-align: right; border-top: 1px solid black;"><b>16,450.29</b></td> </tr> </table>	Labour 1	:	<b>8,338.00</b>	Parts	:	<b>7,036.10</b>	Labour 2	:	<b>0.00</b>	Excess	:	<b>0.00</b>	Total GST @ 7%	:	<b>1,076.19</b>	<b>Grand Total</b>	:	<b>16,450.29</b>
Labour 1	:	<b>8,338.00</b>																	
Parts	:	<b>7,036.10</b>																	
Labour 2	:	<b>0.00</b>																	
Excess	:	<b>0.00</b>																	
Total GST @ 7%	:	<b>1,076.19</b>																	
<b>Grand Total</b>	:	<b>16,450.29</b>																	

**\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\***

**\*\* PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE \*\***