

ASS. REC. BY:

REF:

CS/CTI20003525/KH3 02

Special Instructor

Survey: Annex

ASSIGNMENT (Office)

From (Person): Ben Pang of CTI Date/Time: 3/3/2020

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDS51E Insured: GBE4385Mat Workshop m/s Yee Auto Tel: 64575168of Blk 160 S/M Drive #02-17Policy No: _____ Claim No: SNM200201100

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 29/2/2020
(Client's Record)CA / REV / REP. / REV 24 HRS 4/3/2020 H.O.D. Endorsement: _____Date/Time: 3/3 Person Contacted: _____ Vehicle IN / OUT

Date/Time	Action/Instruction	Followup (✓)
	SDS51E - X	
	GBE4385M - NA	CTI 20003409 24 HOD: 29/2/2020
9/3	LI Pang 8 27ud email & call from	
	(Red: 5059.70! 65%)	

Nivitha (LKK Auto)

From: Ben Tang <Ben.Tang@sg.cntaiping.com>
Sent: Tuesday, 3 March 2020 4:32 PM
To: assignments
Cc: yeeauto pteltd; 'bonnie kwok'; Cecilia Low
Subject: RE: OUR REF: SNM20D201100/GBE4385M/BEN - Pre-Repair Inspection: Your Vehicle: GBE4385M; Our Ref: YeeAuto-SDS51E; Accident Involving SDS 51 E & GBE 4385 M on 29 February 2020

Dear Sirs

We refer to above matter.

Please assist to arrange for PRS survey of TP vehicle SDS51E.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: bonnie kwok <litigation@bonniekwok.com>
Sent: Tuesday, March 3, 2020 4:29 PM
To: Cecilia Low <cecilia.low@sg.cntaiping.com>
Cc: Ben Tang <Ben.Tang@sg.cntaiping.com>; yeeauto pteltd <yeeautopteltd@gmail.com>
Subject: Re: OUR REF: SNM20D201100/GBE4385M/BEN - Pre-Repair Inspection: Your Vehicle: GBE4385M; Our Ref: YeeAuto-SDS51E; Accident Involving SDS 51 E & GBE 4385 M on 29 February 2020

Dear Sirs,

We have been instructed that the repairers have not received any calls from M/s LKK Auto Consultants Pte Ltd yet.

Kindly assist to expedite and ensure that the pre-repairs inspection is conducted within the stipulated time frame.

Regards,
ST

--

Veh In
4/3/2020

BONNIE KWOK LLC

Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 8.45 a.m. to 5.45 p.m. and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Tue, 3 Mar 2020 at 09:43, bonnie kwok <litigation@bonniekwok.com> wrote:

Dear Sirs,

Our client agrees to LKK Auto Consultants Pte Ltd as the Single Joint Expert (SJE).

Please let us have their report in due course.

Kindly request for the SJE to contact the repairers, M/s Yee Auto Pte Ltd at 6457 5768 to make the necessary arrangements.

Regards,
ST

--

BONNIE KWOK LLC

Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 8.45 a.m. to 5.45 p.m. and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Mon, 2 Mar 2020 at 16:28, Cecilia Low <cecilia.low@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sirs

We refer to your email of even date.

We intend to conduct a Pre-Repair Survey of your client's vehicle jointly with your client/your motor workshop.

We propose to use one of the following motor surveyors to conduct the survey as a single joint expert.

LKK / LBS

Adrian Ling
Kelvin Ang
See Chew Seng
Mohd Fadhilah Bin Osman
Xing Quo Qiang
Kenneth Kong
Simon Ho
Chua Weijie
Marcus Chua
Henry Ng

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

Thank you.

Cecilia Low (Ms)

Senior Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6530 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Monday, 2 March 2020 4:26 PM

To: Ben Tang <Ben.Tang@sg.cntaiping.com>; 'bonnie kwok' <litigation@bonniekwok.com>; Cecilia Low <cecilia.low@sg.cntaiping.com>

Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: OUR REF: SNM20D201100/GBE4385M/BEN - Pre-Repair Inspection: Your Vehicle: GBE4385M; Our Ref: YeeAuto-SDS51E; Accident Involving SDS 51 E & GBE 4385 M on 29 February 2020

Dear Cecilia,

Please assist to conduct PRS for SDS51E.

Note : officer in charge – Ben Tang 63896175.

*** Kindly quote our reference number when replying.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: bonnie kwok <litigation@bonniekwok.com>

Sent: Monday, March 2, 2020 2:54 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: Urgent: Pre-Repair Inspection: Your Vehicle: GBE4385M; Our Ref: YeeAuto-SDS51E; Accident Involving SDS 51 E & GBE 4385 M on 29 February 2020

Urgent

Dear Sirs,

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle no. SDS 51 E at M/s Yee Auto Pte Ltd, Block 160 Sin Ming Drive #02-17 Sin Ming Autocity Singapore 575722.

Regards,
ST

--

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 8.45 a.m. to 5.45 p.m. and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other

defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteLtd@gmail.com

Registration No: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Estimate No: ES2000022

Date: 02 Mar 2020

Policy No:

Veh Reg No: SDS51E

Make/Model: TOYOTA ESTIMA
AERAS PREMIUM 2.4 A

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 29/02/2020

TP Veh Reg No: GBE4385M

Not Notarised
61 Sep 82700h
Permyr After Pain
4 days

Chassis No: ACR500192332

Engine No: 2AZ4A08011

Reg. Date: 10/05/2016

Estimate Repair Cost to Vehicle No :SDS51E

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 REAR WHEEL RIM - RH	900.00	1 PC	900.00	X
2 REAR TYRE - RH	500.00	1 PC	500.00	X
			1,400.00	1,400.00
Spare Parts				
3 SLIDING DOOR - RH	1,302.80	1 PC	1,302.80	✓
4 SLIDING DOOR PROTECTOR - RH	865.70	1 PC	865.70	✓
5 REAR FENDER PROTECTOR - RH	289.60	1 PC	289.60	X
6 FRONT DOOR PROTECTOR - RH	865.70	1 PC	865.70	X
7 SLIDING DOOR GLASS OUTER MOULDING - RH	135.90	1 PC	135.90	X
			3,459.70	3,459.70
Labour				
8 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,200.00	1 JOB	1,200.00	400
9 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,200.00	1 JOB	1,200.00	900
10 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	150.00	1 JOB	150.00	30
11 WHEEL ALIGNMENT	120.00	1 T	120.00	X
12 TO REMOVE/TRANSFER SLIDING DOOR MECHANISMS.	150.00	1 JOB	150.00	60
13 TO CHECK WIRING FUNCTIONS.	80.00	1 JOB	80.00	20
			2,900.00	2,900.00
			Total	SS 7,759.70
			Add GST @ 7%	543.18
			Total Amount Payable	SS 8,302.88

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND THREE HUNDRED AND TWO AND CENTS EIGHTY EIGHT ONLY

For Yee Auto Pte Ltd

8639.70

AUTHORISED SIGNATURE



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
 Tel: 6457 5768 Fax: 6252 8459 Mobile 9687 4031
 Email: yeeautopteitd@gmail.com
 Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd
 3 Anson Road
 #16-00 Springleaf Tower
 Singapore 079909

ATTN: Motor Claim Department

Your Ref No:
 Claim Type: Third Party
 Accident Date: 29/02/2020
 TP Veh Reg No: GBE4385M

Estimate No: ES2000022
 Date: 04 Mar 2020
 Policy No:
 Veh Reg No: SDS51E
 Make/Model: TOYOTA ESTIMA
 AERAS PREMIUM 2.4 A
 Chassis No: ACR500192332
 Engine No: 2AZ4A08011
 Reg. Date: 10/05/2016

Estimate Repair Cost to Vehicle No :SDS51E

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
Supplementary Parts to Repair				
Spare Parts				
1 SLIDING DOOR GLASS - RH	780	1 PC	880.00	880.00
	258		880.00	880.00
Total				SS 880.00
GST Amount				SS 61.60
Total Amount Payable				SS 941.60

For Yee Auto Pte Ltd



AUTHORISED SIGNATURE

YEE Auto Consulting Services

Our Register of Services:

- Insurance Claims Assessment
- Vehicle Damage Assessment
- Parts Replacement
- Repairs
- Total Loss
- Salvage

Address: 160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Phone: 6457 5768

Fax: 6252 8459

Email: yeeautopteitd@gmail.com

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20003525/KTF3N2
Date: 16/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30249319022
Claimant Vehicle No : SDS51E **Insured Vehicle No :** GBE4385M
 Date of Loss: 29/02/2020 Nature of Claim: TP Claim No: SNM20D201100

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDS51E**
 Make & Model: TOYOTA ESTIMA, 2.4 (A) Engine No: 2AZ4A08011
 Reg. Date: 10/05/2016 (Man. Year: 2015) Chassis No: ACR500192332
 Colour: Metallic Silver Odometer: 78863 km
 Engine Capacity: 2362 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 3 mm
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,739.70	2,003.10	3,736.60	65.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	1,410.00	1,490.00	51.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,639.70	3,413.10	5,226.60	60.50
Approved Total (Overridden) (S\$)		2,700.00		
	8,639.70	2,700.00	5,939.70	68.75
+ GST 7.00/7.00% (S\$)	604.78	189.00	415.78	68.75
Nett Amount (S\$)	9,244.48	2,889.00	6,355.48	68.75

INSPECTION

Date of Assignment: 11/03/2020
 Date Inspected: 04/03/2020 Inspected At: Yee Auto Service (HQ)
 160 Sin Ming Drive #02-17 Sin Ming Autocity
 Singapore 575722
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Mar 2020)
Parts: M1-MPV	TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDS51E)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WHEEL RIM -RH	Serviceable	900.00 F	*- F
2	1		*REAR TYRE -RH	Serviceable	500.00 F	*- F
3	1		*SLIDING DOOR -RH	Dented / Warped	1,302.80 F	*1,302.80 FL
4	1		*SLIDING DOOR PROTECTOR -RH	Dented / Cut	865.70 F	*588.00 FL
5	1		*REAR FENDER PROTECTOR -RH	Repair	289.60 F	*- FL
6	1		*FRONT DOOR PROTECTOR -RH	Repair	865.70 F	*- FL
7	1		*SLIDING DOOR GLASS OUTER MOULDING -RH	Serviceable	135.90 F	*- FL
8	1		*SLIDING DOOR GLASS -RH	Deep Cut	880.00 F	*780.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,739.70	2,670.80
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	667.70
Total Parts (\$\$)	5,739.70	2,003.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANEL BEAT WHERE NECESSARY	New	1,200.00	400.00
2	TO PUTTY,APPLY PRIMER & SPRAY -PAINT ON THE AFFECTED PORTION	New	1,200.00	900.00
3	TO APPLY RUST-PROOFING ON REPAIRED ,REPLACED PANEL	New	150.00	30.00
4	WHEEL ALIGNMENT	New	120.00	0.00
5	TO REMOVE/TRANSFER SLIDING DOOR MECHANISMS	New	150.00	60.00
6	TO CHECK WIRING FUNCTIONS	New	80.00	20.00
Gross Labour Cost (S\$)			2,900.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >