

Lkh Jasper

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

DATE 31/3/2020

Our Ref :

M/S AIG INSURANCE

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SMA9311J

01)	SPRAY PAINTING	\$	480.00	200
02)	COATING	\$	280.00	80
		\$	760.00	

not allowed
2hr

take the other up
2 hrs.

1/4/20 P/P \$380

LKK Auto Consultants hence notify the Repairer of the following:

- To be resurveyed after spray painting
- To be resurveyed (partial) during resurvey
- To be resurveyed subject to confirmation
- This survey is on a "Without Prejudice" basis
- No other work (part/s) is allowed
- Surplus (part/s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Invoice

2 Jun 2020
Invoice No: IVS11867

ISSUED BY
Ceramic Works LLP
13 Kak Bukit Road 4 #01-29 Danley Biz Centre Singapore 417807
Contact: +65 81893233

ISSUED TO
ALVIN ANG
Contact: +65 97709979

Car Plate Number: SMA9311J

Brand: TOYOTA

Model: TOYOTA CHR

Location: Kaki Bukit

Charges

Other Service \$0.00
Please change description here

TOUCH UP AFFECTED AREA \$180.00

Sub-Total	\$180.00
Tax	\$0.00
Total	\$180.00

Currency: SGD Payment Mode: Cash

Terms and Conditions:

Terms and Conditions

*All payment due upon receipt of invoice

*No refund or transfer of packages purchased unless otherwise stated

*Cheque to be crossed and made payable to "Ceramic Works LLP"

*By providing your contact number with us, you hereby kindly consent Ceramic Works LLP to contact you via SMS and phone for any form of marketing or promotion events from us, not withstanding your number maybe listed on the Do Not Call Registry