

INS. CASE OWNER:

CC 6 / AIG 2000 3604

1 Uds3

LKK:

IDAC:

Surveyor:

Marcus

DOI:

5/3/2020

Date / Time:

5/3/2020

Registered in Merimen:

5/3/2020

Pre-assign / CCU / FTE



Insured Vehicle No. : SDT44X

Claim No. : _____

Name of Insured : Tan Mui Hong

Policy No. : _____

Insured Tel No. : _____ HP: _____

Make / Model : _____

Excess Sec II : S\$ _____ D.O.A : 24/2/2020

Place of Accident : _____

Is driver the owner? (YES / ☒) Nature of Accident : _____

If NO, Driver Name / Age : _____

OI GIA REPORT: ☒ YES / NO ; TP GIA REPORT: ☒ YES / NO

Driver Tel No. : _____ (V/L: YES / NO)

Insured Liability : _____ % Final ? Yes / No

GBF 3607A

INSRS:
WSP: Liu's Brother
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time		STAGE	DATE / PIC
	GBF 3607A : X	Non-Reporting ltr (1st):	
	SDT44X : NA / AIG 2000 3604 / 2/23; D.O.A: 12/2/12	Non-Reporting ltr (2nd):	
	- Kindly verify the OIB's DL.	Non-Reporting ltr (Final):	
23-03-20	TO MAINTAIN REJECTION AND CLOSE FILE.	Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
24/3/20	HLG PAS TO LSL TO WORKS	Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☐
		After call ltr to OI:	☐
		Authorisation To Act:	☐
		Release Voucher:	☐
		Final Repair Bill:	☐
		Car Rental Invoice:	☐
		Towing Invoice	☐
		LTA / GIA :	☐
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☐
		LOD	☐
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	S\$	(days)	Reduction: %
FINAL SETTLEMENT		Date/Time:	Confirm with:
Final Liability:	%	(Agreed / Assessed)	BOLA S/N No. :
Repair Cost:	S\$		
Loss of Rental (LOR):	S\$	(days)	
Loss of Use (LOU):	S\$	(\$ x days)	
Loss of Income (LOI):	S\$	(\$ x days)	
LOR only ☐	LOU only ☐	LOR + LOU ☐	LOR + LOI ☐ [Tick only one]
GIA/LTA Search	S\$		
Medical:	S\$		
Disbursement:	S\$	(e.g. Tow/ Independent)	
Legal Cost	S\$		
Total:	S\$	Global Sum S\$:	
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	S\$	Name 1:	
Payee 2: (Strike if N.A.)	S\$	Name 2:	
Payee 3: (Strike if N.A.)	S\$	Name 3:	

COPY SENT

- 1) Claim status: Normal/Reject/Private Settle
 2) Report Format: ☒ 11
 3) Survey fee: \$320

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbrog@gmail.com

Invoice/Ref No: GBF3607A200224

Estimate

Customer		
Name:	AIG Asia Pacific Insurance Pte Ltd	Date: 04-03-20
Address	Motor Claims Department	Vehicle No: GBF3607A
	78 Shenton Way #07-16	Model/Make: Toyota Hiace DX
	AIG Building	3.0 Manual
	Singapore 079120	

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Lh Head Lamp <i>CNA 780.50</i>	\$ 930.70	<i>✓</i>
2	Fog Lamp Cover <i>CN7</i>	\$ 68.50	<i>✓</i>
3	Bumper Bracket <i>17</i>	\$ 139.10	<i>X</i>
4	Bumper <i>CN7 582.10</i>	\$ 796.80	<i>✓</i>
5	Bumper Clips 1 set <i>new</i>	\$ 50.00	<i>✓</i>
6	Door LTA "Corporate" ROC Detail Sticker <i>new</i>	\$ 48.00	SN 305. <i>✓</i>
7	"Corporate" Advertisement Sticker 1 set <i>new</i>	\$ 300.00	SN 2505. <i>✓</i>
	To check all wiring & electrical component for proper function	\$ 50.00	- 20
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 400.00	- 150
	To putty & spray painting & including touch up paint on accident affected	\$ 400.00	- 200
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 40.00	- 11X

Total Parts & Labour of estimate for damaged vehicle

\$ 3,223.10

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

not allocated
2hr
1/3 x 1400
3 days
The photo after repair
5/3/20

ACKNOWLEDGEMENT FORM

By the receipt of this invoice, the customer acknowledges that the work has been completed and the vehicle has been returned to him/her.

Signature: _____

Date: _____

P- 1484.1
252
1113.07
1763.07
1410.46

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	196N
Vehicle Details	
Vehicle No.:	GBF3607A
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Mar 2020
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX 3.0 MANUAL
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	1KD2600696
Chassis No.:	KDH2010193080
Maximum Power Output:	-
Open Market Value:	\$31,007.00
Original Registration Date:	16 Sep 2016
First Registration Date:	16 Sep 2016
Transfer Count:	1
Actual ARF Paid:	\$1,551.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Sep 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$5,236.00
COE Rebate Amount:	\$3,417.00
Total Rebate Amount:	\$3,417.00

The information contained herein is correct as at 05 Mar 2020

OK



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

May 2015 Mercedes-Benz GL350 AMG Sport At \$203800.



1.98% Financing Rate.
Immaculate Condition. Low
Mileage 71000km. Low Depre
27%
Roadlink Auto - StarAd

HIN LUNG AUTO
Ho Bee Group

30 years
of car sale

One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

17 vehicles

hiace

Advanced Search ✕ Submit !

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	hiace		Any	Any	2016	Any	Any	Any	Available
	Toyota	Hiace Commuter 3.0A GL	\$48,800	\$7,840 /yr	25-May-2016	2,982 cc	-	Bus	Available
Fuel Type: Diesel Please Call To Arrange For Viewing. Thanks. Posted: 04-Mar-2020 Tags: 2016 Toyota Hiace, Toyota Hiace, Toyota, Hiace									
	Toyota	Hiace 3.0A DX	\$53,800	\$8,250 /yr	09-Dec-2016	2,982 cc	-	Bus	Available
Fuel Type: Diesel 1 Careful Owner! Full Accessories! Good Condition! View To Believe! Call Now Before It's Gone! Net Link Partners Pte Ltd Posted: 03-Mar-2020 Tags: 2016 Toyota Hiace, Toyota Hiace, Toyota, Hiace									
	Toyota	Hiace 3.0A	\$47,800	\$7,570 /yr	29-Jun-2016	2,982 cc	-	Van	Available
Fuel Type: Diesel Cheapest In The Market, Monthly \$800, Toyota Hiace 5 Door Auto, Class 3 A Can Drive, Low Mileage. Wonderful Condition, High Trade I... SG Motor Link Pte Ltd Posted: 02-Mar-2020 Tags: 2016 Toyota Hiace, Toyota Hiace, Toyota, Hiace									
	Toyota	Hiace 3.0A	\$49,800	\$7,490 /yr	27-Oct-2016	2,982 cc	47,221 km	Van	Available
Fuel Type: Diesel Top Notch Condition, Accident Free. Previously Own By 1 Owner Only, Well Maintained By Previous Owner. No Repairs Needed! Marvello... Car (S) Pte Ltd Posted: 02-Mar-2020 Tags: 2016 Toyota Hiace, Toyota Hiace, Toyota, Hiace									
	Toyota	Hiace (For Lease)	\$1,400/mth TOYOTA HIACE (A) FOR LEASE (BRAND NEW READY STOCK)						
More info about this vehicle.									
	Toyota	Hiace 3.0A Super GL	\$60,800	\$9,690 /yr	13-Jun-2016	2,982 cc	105,000 km	Bus	Available
Fuel Type: Diesel 100% Loan Available! Instalment As Low As \$975 Monthly. 220 Ready Toyota Hiace Super GL Mid Roof With Modelista Kit! 13+1 Seater... Car (S) Pte Ltd Posted: 29-Feb-2020 Tags: 2016 Toyota Hiace, Toyota Hiace, Toyota, Hiace									
	Toyota	Hiace 3.0A DX	\$59,800	\$8,770 /yr	29-Dec-2016	2,982 cc	-	Bus	Available
Fuel Type: Diesel Standard Roof Bus, Cheap Season Parking Rate, Previous Owner Punctual To Do Servicing Every 10000km Mileage, Very Good Condition... ABWIN Bus Pte Ltd Posted: 26-Feb-2020 Tags: 2016 Toyota Hiace, Toyota Hiace, Toyota, Hiace									

[Compare](#)

Jia Le (LKK Auto)

From: Chan, Kian-Meng <Kianmeng.Chan1@aig.com>
Sent: Monday, 23 March 2020 11:31 AM
To: Jia Le (LKK Auto)
Subject: RE: Your ref: 1951747637SG [ACCIDENT INVOLVING VEHICLES SDT44X AND GBF3607A ON 24/02/2020]

Dear Carlor

Please proceed to reject claim.

Best regards,
Chan Kian Meng
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way, #08-16, Singapore 079120
Tel +(65) 6419 1678
KianMeng.Chan1@aig.com | www.aig.sg

From: Jia Le (LKK Auto) <JiaLe@lkkauto.com>
Sent: Monday, March 23, 2020 10:52 AM
To: Chan, Kian-Meng <Kianmeng.Chan1@aig.com>
Subject: [EXTERNAL] Your ref: 1951747637SG [ACCIDENT INVOLVING VEHICLES SDT44X AND GBF3607A ON 24/02/2020]

This message is from an external sender; be cautious with links and attachments.

Dear Kian Meng,

Based on OI's video footage, he is travelling straight on his own lane, TP change lane and collided onto OI's vehicle rear right portion.

Therefore, we would like to reject TP claim.

Thank you.

Best Regards,
Chan Jia Le | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

FACTS

- T/P VEH. CHANGED LANE FROM RIGHT TO LEFT MOST LANE WITHOUT GIVING WAY AND EXERCISE DUE CARE IS LIABLE FOR THE CAUSE OF ACCIDENT
- O/I WAS TRAVELLING ON LEFT MOST LANE PRIOR TO COLLISION. IT IS DUE TO T/P'S LANE CHANGING FORCEFULLY THEREFORE CAUSING THE COLLISION. THE VIDEO SHOWS CLEARLY THAT O/I WAS ON LEFT MOST LANE WHEN T/P CHANGING LANE. EVEN THOUGH O/I KEPT TO LEFT TO AVOID COLLISION BUT STILL IN VAIN.
- TO MAINTAIN REJECTION OF T/P CLAIM AND CLOSE FILE.

Jia Le (LKK Auto)

From: Chan, Kian-Meng <Kianmeng.Chan1@aig.com>
Sent: Monday, 23 March 2020 11:31 AM
To: Jia Le (LKK Auto)
Subject: RE: Your ref: 1951747637SG [ACCIDENT INVOLVING VEHICLES SDT44X AND GBF3607A ON 24/02/2020]

Dear Carlor

Please proceed to reject claim.

Best regards,
Chan Kian Meng
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way, #08-16, Singapore 079120
Tel +(65) 6419 1678
KianMeng.Chan1@aig.com | www.aig.sg

From: Jia Le (LKK Auto) <JiaLe@lkkauto.com>
Sent: Monday, March 23, 2020 10:52 AM
To: Chan, Kian-Meng <Kianmeng.Chan1@aig.com>
Subject: [EXTERNAL] Your ref: 1951747637SG [ACCIDENT INVOLVING VEHICLES SDT44X AND GBF3607A ON 24/02/2020]

This message is from an external sender; be cautious with links and attachments.

Dear Kian Meng,

Based on OI's video footage, he is travelling straight on his own lane, TP change lane and collided onto OI's vehicle rear right portion.

Therefore, we would like to reject TP claim.

Thank you.

Best Regards,
Chan Jia Le | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Jia Le (LKK Auto)

From: Jia Le (LKK Auto)
Sent: Monday, 23 March 2020 12:32 PM
To: Susan Low
Subject: RE: Your ref: GBF3607A [ACCIDENT INVOLVING VEHICLES SDT44X AND GBF3607A ON 24/02/2020]
Attachments: SDT44X (OI).mp4

Without Prejudice

Dear Susan,

ACCIDENT INVOLVING SDT 44X & GBF 3607A ON 24/02/2020

We refer to the above matter.

Based on our insured's video footage, your client's vehicle changed lane and collided onto our insured's vehicle.

In view of the above, we have our principal instruction to deny liability and unable to look into your client's claim.

Thank you.

Best Regards,

Chan Jia Le | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Susan Low [mailto:liusbro@ymail.com]
Sent: Monday, 23 March 2020 10:47 AM
To: Jia Le (LKK Auto)
Subject: Re: Your ref: GBF3607A [ACCIDENT INVOLVING VEHICLES SDT44X AND GBF3607A ON 24/02/2020]

Thank.

Best Regards,

Susan Low
M/s Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 67411730 Fax: 67445746

On Monday, 23 March 2020, 10:06:21 am SGT, Jia Le (LKK Auto) <jiale@lkkauto.com> wrote:

WITHOUT PREJUDICE

Dear Susan,

We received your GIA report which shows that "reporting only".

Kindly advise whether your client is claiming against us. If so, please let us have a copy of amended GIA report.

Thank you.

Best Regards,

Chan Jia Le | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)
Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Feb 2020 Edit Reg		05 Mar 2020 00:00 Edit Adj Rpt	S\$1,400.00 Edit Estimates	S\$1,400.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS				[Created by adjuster]	
Insured:	TAN MUI HONG, ID: -				
Main Claimant:	GOLDBELL LEASING PTE LTD				
Vehicle Reg. No.:	GBF3607A	Date of Loss:	24/02/2020 00:00 - :59 [41 Months and 8 Days From LTA Reg Date (Man Yr)]		
Claim Type:	TP / 1951747637SG	Policy/Cover Note No.:	2100341327 (Comprehensive)		
Vehicle Reg. No. (Insured):	SDT44X	Policy No. (Claimant):			
		Excess:			
Repairer:	Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit, 417883 Kaki Bukit - Tel:				
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Klan-Meng] Klanmeng.Chan1@aig.com				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 16/03/2020]				

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

• AIG_SG (06/03/2020): NO TP GIA REPORT

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date

Priority

Type

Task Group

Subject

Handler

Assigned By

Completed On

Created On

Done?

No results.

Claim Documents

*GBF3607A (1951747637SG)
[SDT44X]
TP
GOLDBELL LEASING PTE LTD
Feb 24 2020 12:00AM
[TAN MUI HONG]
Liu's Brother Auto Engineering Workshop (kaki Bukit)

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Video

1 per page

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	06/03/20 09:37	Video - Accident	Load MP4	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/03/20 15:24	General View	Load JPG	
2	05/03/20 15:24	General View	Load JPG	
3	05/03/20 15:24	General View	Load JPG	
4	05/03/20 15:24	General View	Load JPG	
5	05/03/20 15:24	General View	Load JPG	
6	05/03/20 15:24	General View	Load JPG	
7	05/03/20 15:24	General View	Load JPG	
8	05/03/20 15:24	General View	Load JPG	
9	05/03/20 15:24	General View	Load JPG	
10	05/03/20 15:24	General View	Load JPG	
11	05/03/20 15:24	General View	Load JPG	
12	05/03/20 15:24	General View	Load JPG	
13	05/03/20 15:24	General View	Load JPG	
14	05/03/20 15:24	General View	Load JPG	
15	05/03/20 15:24	General View	Load JPG	
16	05/03/20 15:24	General View	Load JPG	
17	05/03/20 15:24	General View	Load JPG	
18	05/03/20 15:24	General View	Load JPG	
19	05/03/20 15:24	General View	Load JPG	
20	05/03/20 15:24	General View	Load JPG	
21	05/03/20 15:24	General View	Load JPG	
22	05/03/20 15:24	General View	Load JPG	
23	05/03/20 15:25	Odometer Reading	Load JPG	
24	05/03/20 15:25	Chassis Number	Load JPG	
25	18/03/20 19:07	After Repair Photo	Load JPG	
26	18/03/20 19:07	After Repair Photo	Load JPG	
27	18/03/20 19:07	After Repair Photo	Load JPG	
28	18/03/20 19:07	After Repair Photo	Load JPG	

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/03/20 17:18	TP ESTIMATE-MARKED	Load PDF	
2	23/03/20 10:49	TP GIA REPORT	Load PDF	
3	23/03/20 14:02	reject email from AIG on 23032020	Load PDF	
4	23/03/20 14:02	email to wksp to reject	Load PDF	

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	06/03/20 09:33	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20003604/UDS3Q2
 Date: 30/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100341327
 Claimant: GBF3607A Insured Vehicle No: SDT44X
 Vehicle No: GBF3607A
 Date of Loss: 24/02/2020 Nature of Claim: TP Claim No: 1951747637SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBF3607A
 Make & Model: TOYOTA HIACE, 3.0 D DX (M) Engine No: 1KD2600696
 Reg. Date: 16/09/2016 (Man. Year: 2016) Chassis No: KDH2010193080
 Colour: Blue Odometer: 75371 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
 Front Left Side: GREEN-MAX 6 mm Rear Left Side: GREEN-MAX 6 mm
 Front Right Side: GREEN-MAX 6 mm Rear Right Side: GREEN-MAX 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,333.10	1,393.07	940.03	40.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	890.00	370.00	520.00	58.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,223.10	1,763.07	1,460.03	45.30
Approved Total (Overridden) (\$\$)		1,400.00		
Nett Amount (\$\$)	3,223.10	1,400.00	1,823.10	56.56
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 05/03/2020
 Date Inspected: 05/03/2020 Inspected At: Liu's Brother Auto Engineering
 Workshop (kaki Bukit) (HQ)
 Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay
 @ Kaki Bt Singapore 417883, Kaki
 Bukit
 Singapore 417883
 Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH HEAD LAMP	Cracked	930.70 F	*780.50 FL
2	1		*FRONT LH FOG LAMP COVER	Cut	68.50 F	*68.50 FL
3	1		*FRONT LH BUMPER BRACKET	Not Necessary	139.10 F	*- FL
4	1		*FRONT LH BUMPER	Cut	796.80 F	*585.10 FL
5	1		*SET FRONT LH BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
6	1		*FRONT LH DOOR LTA CORPORATE ROC DETAIL STICKER	Necessary	48.00 FS	*30.00 FS
7	1		*SET FRONT LH CORPORATE ADVERTISEMENT STICKER	Necessary	300.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,333.10	1,764.10
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	371.03
Total Parts (S\$)	2,333.10	1,393.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	20.00
2	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	400.00	150.00
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	400.00	200.00
4	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	40.00	0.00
Gross Labour Cost (S\$)			890.00	370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >