

Estimate

Vehicle: SJD 4836P

Make & Model: TOYOTA SIENNA

Year: _____

Chassis no: _____

Qty	Parts / Labour	Cond	Part \$
1	PN side mirror housing	✓	630
1	Signal Lamp	✓	180
1	cover	✓	120
1	GLASS	+	135
1	RH DRIVER Door Regis	+	1,150
	labour panel beat	100	400
	spring paint	300	400
	Remove & Refit Door Attachments	x	150

PRO-JEX V2D MOTOR PTE LTD

Reg. No.: 201600429G


SYNERGY @ KB

25 KAKI BUKIT ROAD #03-94

SINGAPORE 417800

HOTLINE: 6100 7676

FAX : 6841 9698



list: 930

25%: 697.50

labour: 400

total: 1097.50

HS: 850

Adrian Lij
L/S 23/03/20

02 days.

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: