

ASS. REC. BY:

REF:

es/smo20003610/4td3n2

Special Instruction:

Singapore: MORUS

ASSIGNMENT (Office)

From (Person): Gmce Teo

of SMO

Date/Time: 5/3/2020 @ 8:45am

Estimated Cost:

Bill to:

OH / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBJ 8640Z

Insured:

YN1597T

at Workshop m/s

Liu's Brother

Tel: 67411730

of

1 Kaki Bukit Ave 6 # 01-01 Autobay

Policy No:

Claim No:

CMTD2000768/844

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 02/03/2020

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time:

1:27am @ 5/3/2020

Person Contacted:

Sueen

Vehicle IN / OUT

Date/Time

Action/Instruction

Johnydg ✓

GBJ 8640Z - X

YN1597T - X

9/3@10:13am sent preli advice via email.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: GRJ 86402
 at Workshop m/s 1st's Auto
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record) _____
 Make of Veh: _____

Veh No: GRJ 86402 Yr Regn: 9/19
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or (M)
 Make: Toyota Dyne C.C. 2982
 Colour: orange A/C: Insured / Std / NI / NA
 Sp. Reading: 4668 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTFAT35410K213823
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Insured / Jammed / Leaked / Burnt or
 Brake: Insured / Jammed / Leaked / Burnt or
 Mod: NI / S/Rim / STD A/Rim or

Tyre Size: F: 195/75 R15
 R: 155 R12
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

N/S	O/S

Front 6 mm Rear 6/6 mm
 R/Bal. 6 mm L/Bal. 6/6 mm
 D.O.A. 2/3/20 D.O.I. 5/3/20
 Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

0/5 Lf.
 The UIC / Chassis frame / Body Structure affected due to collision

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection

Bal. or Market Value:

60k.

IDAC Accident Report:

Consistent? : Yes or No

G/A / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

LTA 22/51

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

fil der 1605-45

11/3/20 1/5 @ 1900 conf. and with Susan. (Red: 1871.40; 49%)

RECEIVED 12 MAR 2020

Date/Time, File Pass to?



Prel. Report

Days Of Repair: 41) 12/3 Typist

Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee:



Site Insp (\$

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$ 1900/-)

TOTAL

250



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD2000968/SYH

Date: 09/03/2020

Our Ref: CS/SMO20003610/Utd3

The Motor Claims Department
SOMPO INSURANCE SINGAPORE P

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. GBJ 8640Z

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 05/03/2020 at the premises of M/s Liu's brother and have the following to report: -

Workshop Estimate Amount	: S\$ <u>3,771.40</u>
Revised Estimate Amount	: S\$ <u>2,770.05</u>
"Check" Items Amount	: S\$ <u>0.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the o/s front portion.



Repair days: 4

Comments/ Present Status:

Damages Consistent.

Yours faithfully

Marcus Chua

Automotive Assessor

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Thursday, 5 March 2020 8:45 AM
To: Liu's Brother; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'; sur@lkkauto.com; Hwang, Shiang Yi
Subject: CMTD2000968/SYH - PRI/ YN1597T & GBJ8640Z ACC ON 02.03.20
Attachments: GBJ8640Z200302.pdf

Our Reference: CMTD2000968/SYH

Your Reference: GBJ8640Z

Without Prejudice

EMAIL ONLY

Date: 05/03/2020

OUR Email: motorsurvey@sompo.com.sg

Attention:

M/S LIU'S BROTHER AUTO ENGINEERING WORKSHOP

Dear Susan,

ACCIDENT INVOLVING YN1597T & GBJ8640Z ON 02.03.2020

We refer to your email reply of 04.03.2020

We will appoint **LKK Auto** to conduct the survey.

Hi **LKK Auto**,

Please make the arrangement to survey for **GBJ8640Z** on a without prejudice and any admission of liability basis.

Please be informed that Ms. Hwang Shiang Yi is the handler of this case who can be contacted at 63295 205/
shiangyi.hwang@sompo.com.sg.

Please revert your report upon completion of survey to my colleague, Ms. Shiang Yi.

Thank you.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555

For motor claims survey request, please email to motorsurvey@sompo.com.sg



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Liu's Brother <liusbro@ymail.com>

Sent: Wednesday, March 4, 2020 9:01 PM

To: Teo, Grace <grace.teo@sompo.com.sg>

Subject: Re: CMTD2000968/SYH - PRI/ YN1597T & GBJ8640Z ACC ON 02.03.20

We did liked to chose as follow

LKK AUTO CONSULTANTS PTE LTD

Kindly arrange

Thank

Best Regard

Susan Low

M/s Liu's Brother Auto Engineering Workshop

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit

Singapore 417883 ☎: 6741 1730 📠: 6744 5746

On 4 Mar 2020, at 15:55, Teo, Grace <grace.teo@sompo.com.sg> wrote:

Our Reference: CMTD2000968/SYH

Your Reference: GBJ8640Z

Date: 04/03/2020

Without Prejudice
EMAIL ONLY

OUR Email: motorsurvey@sompo.com.sg

Attention:

M/S LIU'S BROTHER AUTO ENGINEERING WORKSHOP

Dear Susan,

ACCIDENT INVOLVING YN1597T & GBJ8640Z ON 02.03.2020

We refer to your Notice of Accident dated 04/03/2020.

Please be informed that **Ms. Hwang Shiang Yi** is the handler of this case who can be contacted at 63295 205/ shiangyi.hwang@sompo.com.sg.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555

For motor claims survey request, please email to motorsurvey@sompo.com.sg

<image001.png>

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @

<image006.png>

or

<image007.png>

* ¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.
Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Susan Low <liusbro@ymail.com>

Sent: Wednesday, March 4, 2020 3:27 PM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>; Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>

Subject: Request for 3rd party claims survey GBJ8640Z Claims against YN1597T

Accident on 02/03/2020 Along 19 Greenwich Drive Lot Number (KDS2)

Involving GBJ8640Z and YN1597T

We refer to the above accident and 3rd party claims.

We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.

Please let us have your single joint expert motor surveyors list (SJE) to conduct a pre-repair survey of the damage to our client's vehicle jointly with our client/our motor workshop at No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883 as soon as possible.

Kindly arrange.

Thank you.

Best Regard!

Susan Low
M/s Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 6741 1730
Fax: 6744 5746

Date of Survey:-

Name of Authorise Surveyor:-

Surveyor Email:

Remark :-

Petrol Price Movement in Singapore

Air purifier for car

Shift to new satellite base ERP system in 20...

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

2015 Lexus ES Hybrid ES300h Luxury \$103.8K



Promo Rate 1.98%, Agent
Warranty For 5 Year + 10 Year
Hybrid Warranty.
[Trust Motoring](#) [StarAd](#)



click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Browse by Category ▼

« Back (1 2 3) Next »

Sort by Date Posted ▼ 20 results/page ▼

41 vehicles

Dyna

Advanced Search  Submit 

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Dyna		Any	Any	2019	Any	Any	Any	Available



Toyota Dyna 150 3.0M **\$63,988** **\$6,540 /yr** **17-Dec-2019** **2,982 cc** **-** **Truck** **Available**
Fuel Type: Diesel
Latest Euro 6 Toyota Dyna, Ready Unit, 5 Years Warranty And Free 8 Times Servicing, Free Front Record Camera, Free Reverse Sensor,...
ABWIN Bus Pte Ltd
Posted: 05-Mar-2020 Tags: 2019 Toyota Dyna, Toyota Dyna, Toyota, Dyna



Toyota Dyna 150 3.0M **\$65,988** **\$6,890 /yr** **01-Oct-2019** **2,982 cc** **-** **Truck** **Available**
Fuel Type: Diesel
Monthly \$760 Or \$1K To Driveaway. Rare Deal! Price No Gimmicks, No Admin Fee, No Hidden Cost. New 10 Year COE & GST Inclusive...
ABWIN Bus Pte Ltd
Posted: 05-Mar-2020 Tags: 2019 Toyota Dyna, Toyota Dyna, Toyota, Dyna



Toyota Dyna 150 3.0M **\$65,800** **\$7,200 /yr** **24-Apr-2019** **2,982 cc** **-** **Truck** **Available**
Fuel Type: Diesel
Immediate Delivery! Full Agent Warranty And Servicing Package! Latest Euro 6!
Net Link Partners Pte Ltd
Posted: 05-Mar-2020 Tags: 2019 Toyota Dyna, Toyota Dyna, Toyota, Dyna



Toyota Dyna 150 3.0M **\$64,800** **\$7,130 /yr** **05-Apr-2019** **2,982 cc** **-** **Truck** **Available**
Fuel Type: Diesel
Offer Price And Package Till End Of The Month! Best Selling 10 Feet Manual Work Horse Ever In The Market! Trusted And Reputable Mo...
Net Link Partners Pte Ltd
Posted: 05-Mar-2020 Tags: 2019 Toyota Dyna, Toyota Dyna, Toyota, Dyna



3A Car Mat
No.1 Selling Car Mats In Singapore! Customize Car Mats At For Toyota Dyna 2005-2008 your Favourite Colours!
[More info about this product](#)



Toyota Dyna 150 3.0M **\$67,500** **\$6,900 /yr** **16-Dec-2019** **2,982 cc** **-** **Truck** **Available**
Fuel Type: Diesel
Almost New Unit From Agent. Warranty And Free Servicing Packages From Agent. In-house Loan Available. Full Loan Can Be Arranged....
Bell Auto Pte Ltd
Posted: 05-Mar-2020 Tags: 2019 Toyota Dyna, Toyota Dyna, Toyota, Dyna



Toyota Dyna 150 3.0M **\$65,988** **\$7,010 /yr** **02-Aug-2019** **2,982 cc** **-** **Truck** **Available**
Fuel Type: Diesel
Monthly \$777. Package Available To Inclusive 10 Years COE, 1st Year Insurance, 1st Year Road Tax, 1st Year Servicing, Flexible Bank/In...
ABWIN Bus Pte Ltd
Posted: 04-Mar-2020 Tags: 2019 Toyota Dyna, Toyota Dyna, Toyota, Dyna

[Compare](#)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 196N

Vehicle Details

Vehicle No.: GBJ8640Z

Vehicle to be Exported: No

Intended Deregistration Date: 05 Mar 2020

Vehicle Make: TOYOTA

Vehicle Model: DYNA 150 5MT

Primary Colour: White

Manufacturing Year: 2019

Engine No.: 1KD2861152

Chassis No.: JTFAT35Y10K213823

Maximum Power Output: -

Open Market Value: \$27,082.00

Original Registration Date: 12 Sep 2019

First Registration Date: 12 Sep 2019

Transfer Count: 0

Actual ARF Paid: \$1,355.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 11 Sep 2029

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$23,277.00

COE Rebate Amount: \$22,151.00

Total Rebate Amount: \$22,151.00

The information contained herein is correct as at 05 Mar 2020

OK



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-20-038041
Date of Request: 04/03/2020

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP
1 Kaki Bukit Ave 6 #01-01
Auto Bay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date: 04/03/2020
Enquiry By: Susan Low Siew Yian
TP Vehicle No: YN1597T
Accident Date: 02/03/2020

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
YN1597T	Sompo Insurance Singapore Pte. Ltd.	18/08/2019-17/08/2020	6461 6555

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-20-038041

Date of Request: 04/03/2020

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP
1 Kaki Bukit Ave 6 #01-01
Auto Bay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date: 04/03/2020

Enquiry By: Susan Low Siew Yian

TP Vehicle No: YN1597T

Accident Date: 02/03/2020

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 196N

Vehicle Details

Vehicle No.: GBJ8640Z
Vehicle to be Exported: No
Intended Deregistration Date: 04 Mar 2020
Vehicle Make: TOYOTA
Vehicle Model: DYNA 150 SMT
Primary Colour: White
Manufacturing Year: 2019
Engine No.: 1KD2861152
Chassis No.: JTFAT35Y10K213823
Maximum Power Output: -
Open Market Value: \$27,082.00
Original Registration Date: 12 Sep 2019
First Registration Date: 12 Sep 2019
Transfer Count: 0
Actual ARF Paid: \$1,355.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 11 Sep 2029
COE Category: C - Goods Vehicle & Bus
COE Period (Years): 10
PQP Paid: \$23,277.00
COE Rebate Amount: \$22,158.00
Total Rebate Amount: \$22,158.00

The information contained herein is correct as at 04 Mar 2020

OK

LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53201793 | Tel: 6744-1730 / 731 | Fax: 6744-5746 | Email: liusbros@gmail.com

Invoice/Ref No: GBJ8640Z100702

Estimate

Customer

Name: Sompo Insurance Singapore Private Limited

Date: 04-03-20

Address Motor Claims Department

Vehicle No: GB18640Z

50 Raffles Place #05-01 / 06

Model/Make: Toyota Dyna 150

Singapore Land Tower	Singapore 048623
----------------------	------------------

$$5 \text{ MT}$$

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Rh Door <i>500</i>	\$ 1,568.30	<i>4</i>
2	Door Handle <i>scr 210.28 25%</i>	\$ 689.50	<i>4</i>
3	Side Mirror <i>cu7</i>	\$ 195.60	<i>4</i>
4	Door LTA "Corporate" ROC Detail Sticker <i>ner</i>	\$ 48.00	SN 30 5-
5	Door "Corporate" Advertisement Sticker 1 set <i>ner</i>	\$ 200.00	SN 120 5-
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 500.00	- 380
	To putty & spray painting & including touch up paint on accident affected area	\$ 450.00	- 320
	To remove, replace and transfer door panel, fitting and mechanisms	\$ 80.00	- 50
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 40.00	- 30

Total Parts & Labour of estimate for damaged vehicle

\$ 3,771.40

Total amount in Lump Sum Basis for repaired vehicle	
1	2
3	4
5	6
7	8
9	10
11	12
13	14
15	16
17	18
19	20
21	22
23	24
25	26
27	28
29	30
31	32
33	34
35	36
37	38
39	40
41	42
43	44
45	46
47	48
49	50
51	52
53	54
55	56
57	58
59	60
61	62
63	64
65	66
67	68
69	70
71	72
73	74
75	76
77	78
79	80
81	82
83	84
85	86
87	88
89	90
91	92
93	94
95	96
97	98
99	100



SDLS:

M/s Liu's Brother Auto Engrg Wks

not Authorized
Link
Take photo before pa. only
5/3/20
4 days.
2/5 to 1900

P-1974.18
 25%
P-1480.63
 S.W.-150.00
 L-780.00
2410.63
 207
1928




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO20003610/Utd3n2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 13-03-2020		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 1597T	Veh. Inspected	GBJ 8640Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2000968/SYH	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	05/03/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTFAT35Y10K213823	Colour	ORANGE	
Odometer	4668	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/75 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195/75 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	155 R12 (D)	BRIDGESTONE	6/6 mm	
L/H Rear Tyre	155 R12 (D)	BRIDGESTONE	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/03/2020	Inspection Date	05/03/2020	
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 8640Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT RH DOOR	BADLY DENTED	1,568.30	1,568.30
1	FRONT RH DOOR HANDLE	SCRATCHED	689.50	210.28
1	FRONT RH SIDE MIRROR	CUT	195.60	195.60
	LESS 25% DISCOUNT		-	-493.55
			2,453.40	1,480.63
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT RH DOOR LTA "CORPORATE" ROC DETAIL STICKER (SN)	NECESSARY	48.00	30.00
1	SET FRONT RH DOOR "CORPORATE" ADVERTISEMENT STICKER (SN)	NECESSARY	200.00	120.00
			248.00	150.00
	<u>LABOUR</u>			
	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETC.		500.00	380.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA.		450.00	320.00
	TO REMOVE,REPLACE AND TRANSFER DOOR PANEL,FITTING AND MECHANISMS.		80.00	50.00
	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.		40.00	30.00
			1,070.00	780.00
	GRAND TOTAL		3,771.40	2,410.63
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,900.00

Report Ref No. CS/SMO20003610/Utd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.