

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TP FWD

Xiao Tony

ESTIMATE

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 97523456

Repair Code : CLM16111

Date in : 05/03/2020

Vehicle Num. : SLR7906D

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31254273/LEB5954290

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR AXLE Bent	1	1650.00	✓ 1,650.00
REAR LH DOOR Dented.	1	930.60	✓ 930.60
REAR LH DOOR BLACK TAPE New	1	35.00	✓ 35.00
REAR LH DOOR TRANSPARENT New	1	35.00	✓ 35.00
REAR LH DOOR WEATHER STRIP New	1	98.00	+ 98.00
REAR LH DOOR WEATHER STRIP (LOWER) New	1	65.00	+ 65.00
REAR LH DOOR WEATHER STRIP (VERTICAL) New	1	65.00	+ 65.00
REAR LH FENDER ARCH GARNISH New	1	195.00	✓ 195.00
REAR LH SPORT RIM New	1	850.00	✓ 850.00
REAR LH WHEEL BEARING New	1	263.50	✓ 263.50
ROCKER GARNISH LH New	1	377.50	✓ 377.50
Subtotal before discount			4,564.60
Percentage discount 20%			912.92
Sub-total 1			3,651.68
REAR LH FENDER ARCH GARNISH CLIPS - SET New	1	40.00	20 40.00
ROCKER GARNISH CLIPS LH - SET New	1	50.00	30 50.00

*** This is a computer-generated document which requires no signature.***

AN-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No : +65 6842 0051 Fax No : +65 6741 0510
E-Mail : sales@an51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 97523456

ESTIMATE

Repair Code : CLM16111

Date in : 05/03/2020

Vehicle Num. : SLR7906D

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31254273/LEB5954290

Subtotal before discount	90.00
Percentage discount 0%	0.00
Sub-total 2	90.00
Parts-total	3,741.68

LABOUR

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

To road test driving, check and resetting wheel alignments system.

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	1,960.00
Parts & Labour Total	5,701.68

280
~~380.00~~
80. 120.00
✓ 80.00
200 800.00
250 500.00
+ 80.00

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian G
L/S 06/03/20.
04 Days.
Total: 42109.28.
L/S: 3.5K ✓