

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBC9585E200302

Final Bill**Customer**

Name: AIG Asia Pacific Insurance Pte Ltd

Address Motor Claims Department

78 Shenton Way #07-16

AIG Building Singapore 079120

Date: 19-03-20

Vehicle No: GBC9585E

Model/Make: Fiat Doblo 1.6D

Cargo MJ (M)

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bumper	\$ 627.00	\$ -
2	Bumper Clips 1 set	\$ 50.00	\$ -
3	Bumper Reinforcement	\$ 475.30	\$ -
4	Bumper Reverse Sensor 1 set	\$ 220.00	\$ -
5	End Panel	\$ 620.00	\$ -
	To check all wiring & electrical component for proper function	\$ 50.00	\$ -
	Remove and refix rear bumper reverse sensor	\$ 120.00	\$ -
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 400.00	\$ -
	To putty & spray painting & including touch up paint on accident affected area	\$ 500.00	\$ -

Total Parts & Labour of estimate for damaged vehicle

\$ 3,062.30

Total amount in Lump Sum Basis for repaired vehicle

\$ 1,600.00

SDLS: One Thousand Six Hundred Only



M/s Liu's Brother Auto Engrg Wks