



Your Ref : C10005809/LA

Date: 13<sup>th</sup> March 2020

Our Ref : CS/AGI20003741/Uyd3s2

**M/s Auto & General Insurance (Singapore) Pte Ltd**

(Budget Direct Insurance)

190 Clemenceau Avenue #03-01

Singapore Shopping Centre

Singapore 239924

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMG 7274P  
ACCIDENT ON 05/03/2020**

Instruction was received to inspect the vehicle Reg. No. SMG 7274P. The inspection was conducted on 09/03/2020 at the premises of M/s SME Motor Pte Ltd, 1 Kaki Bukit Ave 6 #02-15 (Autobay @Kaki Bukit) Singapore 417883.

The following vehicle information was recorded:

Registration Number	: SMG 7274P
Make/Model	: Honda Shuttle Hybrid (A)
Year of Registration	: 2018
Body Colour	: Red
Chassis Number	: GP72000433
Engine Capacity	: 1496 cc

The vehicle caught fire. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$ 75,000.00
Less: LTA Reimbursement Value (RV)	(S\$ 38,395.00)
Nett Liability	<u>S\$ 36,605.00</u>

Vehicle Inspected By:



CHUA KANG SENG  
Licensed Appraiser



K.K. LAU  
MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),  
AM CATARI(CAN), M. MATA(USA), M. MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.