

REPAIRING OF
MOTOR VEHICLES,
PANEL BEATING,
WELDING, SPRAYING,
INSURANCE AGENT,
CLAIMS
DEALING IN 2ND
HAND VEHICLE.

速 良 摩 哆 SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT
1 Kaki Bukit Ave 6 Blk D 01-91, Singapore 417883
Tel: 6747 7858, 6747 2343 Fax: 6742 0012
E-mail: slmoi@singnet.com.sg
Reg No. 206639/00K

修理汽車貨車兼
打嗎甲燒杆噴漆
代理保險：車禍
賠償及買賣汽車

MR HO PHIAK JOO

DATE: 09/03/2020

DOA : 03/03/2020

ESTIMATE REPAIR FOR VEHICLE NO. SMJ 2091 S (MERCEDES C180)

	Description	List Price
1 pc	Rear bootlid logo	\$ 65.00
1 pc	C180 emblem	\$ 102.00
1 pc	Rear bumper	\$ 2,140.00
2 pcs	Rear bumper side retainer @S\$75.00	\$ 150.00
1 pc	Rear bumper reinforcement	\$ 820.00
1 pc	Rear bumper lower garnish	\$ 270.00
1 pc	Bumper chrome centre	\$ 310.00
4 pcs	Bumper centre reverse sensor @S\$216.00	\$ 864.00
1 pc	Bumper centre sensor seal	\$ 25.00
1 pc	Taillamp	\$ 908.00
1 pc	Headlamp (rh)	\$ 2,980.00
1 pc	Front bumper	\$ 1,880.00
1 pc	Radiator grille	\$ 165.00
1 pc	Radiator carrier	\$ 190.00
1 pc	Logo	\$ 160.00
1 pc	Logo inner base	\$ 95.00
4 pcs	Radiator centre moulding @S\$102.00	\$ 408.00
1 pc	No. plate garnish	\$ 160.00
		\$ 11,692.00
	Less : 10%	\$ (1,169.20)
		\$ 10,522.80
	<u>Special Nett Items</u>	
1 set	No. plate & housing	\$ 60.00
	To remove & fix reverse sensor	\$ 80.00
	To spray anti-rust	\$ 100.00
	Labour charges for knocking & replacing parts.	\$ 1,300.00
	Spraypainting	\$ 1,200.00
	TOTAL :	\$ 13,262.80