

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AIG	DATE	: 11/03/2020
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLF1819A		
MODEL	: MIT ASX 2.0		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 3-Mar-20
		TIME	: 1610HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
14	REAR BUMPER <i>Del d</i>	1	\$ 1,150.30	\$ 1,150.30

TOTAL PRICE \$ 1,150.30

LESS 10% \$ 115.03

SUB TOTAL PRICE \$ 1,035.27

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL S/NETT
1	REAR BUMPER CLIPS(SET) <i>per</i>	1	\$ 20.00	\$ 20.00

Reverse sensor Dangled

TOTAL \$ 20.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 400.00	200
2	TO SPRAY PAINT ON AFFECTED AREA	\$ 400.00	200
3	TUFF COAT	\$ 150.00	x
4	WIRING CHECK	\$ 150.00	x
5	TO REMOVE AND REFIX REVERSE SENSOR AND SETTING	\$ 100.00	40

TOTAL

\$1,200.00

440

ESTIMATE REPORT

TOTAL PARTS COST : \$ 1,055.27
TOTAL LABOUR COST : \$ 1,200.00
TOTAL REPAIR COST : \$ 2,255.27

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian Lj
P/P 11/03/20
03 Pays.

total: 1695.27 (P/P) ✓

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: