

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0253/2020/GW
Date : 10-Mar-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Goh Miah Wee
Address : 135 Serangoon Ave 3
#08-09
Singapore 556114
Telephone : HP +65 88286662
Type of Claim : Own Damage Claims
Policy No. : 1800079209
Vehicle No : **SMA 8682 U**
Model Code : Audi A3 Sedan 1.0 TFSI
Model / Year : Jun-18
Engine No : CHZ 940565
Chassis No : WAUZZZ8V1J1066907
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 05-Mar-20
Place of Accident : HDB Car Park Near BLK 90 HDB Pipit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMA 8682 U

S/N	Nature of Jobs	Estimated Charges
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 360.00 /
2	To dismantle and renew front bumper and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 1,400.00 500
3	To respray front bumper and lhs front fende and bonnet.	\$ 2,800.00 550
4	To carry out diagnostic checks.	S/N \$ 192.00 /
TOTAL LABOUR CHARGES		: \$ 4,752.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 8682 U

Store 16/3/22

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>✓ BR</i>	\$ 1,894.00	
2	FRONT BUMPER FIXING PARTS <i>?</i>	\$ 176.00	
3	FRONT BUMPER GUIDE SECTION-LH <i>✓ BR</i>	\$ 36.00	
4	FRONT BUMPER GRILLE-CENTER <i>X</i>	\$ 151.00	
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>? ✓ BR</i>	\$ 505.00	
6	FRONT BUMPER CLOSING ELEMENT-LH <i>?</i>	\$ 280.00	
7	FRONT BUMPER COVER TRIM-LH <i>?</i>	\$ 153.00	
8	FRONT BUMPER ADAPTER WHEEL HOUSING LINER-LH <i>✓ MC</i>	\$ 36.00	
9	RADIATOR GRILLE <i>✓ BR</i>	\$ 1,338.00	
10	FRONT BUMPER CLOSING ELEMENT <i>?</i>	\$ 180.00	
11	FRONT AIR GUIDE GRILLE-LH <i>?</i>	\$ 177.00	
12	FRONT BUMPER REINFORCEMENT BAR <i>X</i>	\$ 691.00	
13	FRONT FOAM FILLIER PIECE <i>X</i>	\$ 178.00	
14	FRONT BUMPER COVER TRIM-LH <i>?</i>	\$ 115.00	
15	FRONT SIGNAL HORN-LH <i>X</i>	\$ 188.00	
16	LED HEADLIGHT -LH <i>?</i>	\$ 5,193.00	
17	LED HEADLIGHT LIFT CYLINDER-LH <i>?</i>	\$ 134.00	
18	HOSE FOR HEADLIGHT WASHER SYSTEM <i>X</i>	\$ 64.00	
19	WASH WATER RESERVOIR <i>X</i>	\$ 190.00	
20	RADIATOR AIR GUIDE -LH <i>?</i>	\$ 23.00	

SUB-TOTAL SPARE PARTS CHARGES

: \$ 11,702.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 8682 U

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	RADIATOR AIR GUIDE-UPPER CENTER X	\$ 12.00	
22	FRONT WHEEL HOUSING LINER-LH / TN	\$ 159.00	
23	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS / MK	\$ 84.00	
24	FRONT CAR PLATE NO. X	S/N \$ 60.00	
25	SUNDRIES 7	\$ 300.00	
TOTAL SPARE PARTS CHARGES		: \$ 12,317.00	
TOTAL LABOUR CHARGES		: \$ 4,752.00	
GRAND TOTAL		: \$ 17,069.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183


11/3/2020

Telefax

Name

:

Steve (LKK)

DD- Not Authorised (Revised)

Surveyed Date

:

Excess - ?

Authorised Date

:

Excess Cost

:

P/P

Liability

:

By B/L sy

Remarks

:

3 days

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
- For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant