

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: [Nora.khai@premiumauto.com.sg](mailto:Nora.khai@premiumauto.com.sg) / [claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)

**WIP : 32209**

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/0253/2020/GW  
**Date** : 10-Mar-20

**Vehicle NOT IN workshop. Please arrange for survey**

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

*Hi Steve  
4 Days exclude 1 Sunday  
jb 14 May 20*

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr. Goh Miah Wee  
**Address** : 135 Serangoon Ave 3  
#08-09  
Singapore 556114  
**Telephone** : HP +65 88286662  
**Type of Claim** : Own Damage Claims  
**Policy No.** : 1800079209  
**Vehicle No** : **SMA 8682 U**  
**Model Code** : Audi A3 Sedan 1.0 TFSI  
**Model / Year** : Jun-18  
**Engine No** : CHZ 940565  
**Chassis No** : WAUZZZ8V1J1066907  
**Mileage** : -  
**Date In** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 5-Mar-20  
**Place of Accident** : HDB Car Park Near BLK 90 HDB Pipit

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SMA 8682 U

| S/N Nature of Jobs   |                                                                                                                                                   | Estimated Charges |    |          |             |
|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|----|----------|-------------|
| 1                    | To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid. | S/N               | \$ | 360.00   | \$ 360.00   |
| 2                    | To dismantle and renew front bumper and lhs headlight. Re-organise crash management components. Reinstall all parts removed.                      |                   | \$ | 1,400.00 | \$ 500.00   |
| 3                    | To respray front bumper and lhs front fende and bonnet.                                                                                           |                   | \$ | 2,800.00 | \$ 550.00   |
| 4                    | To carry out diagnostic checks.                                                                                                                   | S/N               | \$ | 192.00   | \$ 192.00   |
| TOTAL LABOUR CHARGES |                                                                                                                                                   | :                 | \$ | 4,752.00 | \$ 1,602.00 |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SMA 8682 U

| S/N                                  | Parts Description                           | Damage Parts & Prices |                    |
|--------------------------------------|---------------------------------------------|-----------------------|--------------------|
|                                      |                                             | S/Nett                | Remarks            |
| 1                                    | FRONT BUMPER                                | \$ 1,894.00           | \$ 1,515.20        |
| 2                                    | FRONT BUMPER FIXING PARTS                   | \$ 176.00             |                    |
| 3                                    | FRONT BUMPER GUIDE SECTION-LH               | \$ 36.00              | \$ 28.64           |
| 4                                    | FRONT BUMPER GRILLE-CENTER                  | \$ 151.00             |                    |
| 5                                    | FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE   | \$ 505.00             | \$ 404.00          |
| 6                                    | FRONT BUMPER CLOSING ELEMENT-LH             | \$ 280.00             |                    |
| 7                                    | FRONT BUMPER COVER TRIM-LH                  | \$ 153.00             |                    |
| 8                                    | FRONT BUMPER ADAPTER WHEEL HOUSING LINER-LH | \$ 36.00              | \$ 28.16           |
| 9                                    | RADIATOR GRILLE                             | \$ 1,338.00           | \$ 1,070.40        |
| 10                                   | FRONT BUMPER CLOSING ELEMENT                | \$ 180.00             |                    |
| 11                                   | FRONT AIR GUIDE GRILLE-LH                   | \$ 177.00             |                    |
| 12                                   | FRONT BUMPER REINFORCEMENT BAR              | \$ 691.00             |                    |
| 13                                   | FRONT FOAM FILLIER PIECE                    | \$ 178.00             |                    |
| 14                                   | FRONT BUMPER COVER TRIM-LH                  | \$ 115.00             |                    |
| 15                                   | FRONT SIGNAL HORN-LH                        | \$ 188.00             |                    |
| 16                                   | LED HEADLIGHT -LH                           | \$ 5,193.00           |                    |
| 17                                   | LED HEADLIGHT LIFT CYLINDER-LH              | \$ 134.00             |                    |
| 18                                   | HOSE FOR HEADLIGHT WASHER SYSTEM            | \$ 64.00              |                    |
| 19                                   | WASH WATER RESERVOIR                        | \$ 190.00             |                    |
| 20                                   | RADIATOR AIR GUIDE -LH                      | \$ 23.00              |                    |
| <b>SUB-TOTAL SPARE PARTS CHARGES</b> |                                             | <b>\$ 11,702.00</b>   | <b>\$ 3,046.40</b> |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMA 8682 U

| S/N                              | Parts Description                          | Damage Parts & Prices |                    |
|----------------------------------|--------------------------------------------|-----------------------|--------------------|
|                                  |                                            | S/Nett                | Remarks            |
|                                  |                                            | <i>c/f</i>            | <b>\$ 3,046.40</b> |
| 21                               | RADIATOR AIR GUIDE-UPPER CENTER            | \$ 12.00              |                    |
| 22                               | FRONT WHEEL HOUSING LINER-LH               | \$ 159.00             | <b>\$ 127.20</b>   |
| 23                               | FRONT WHEEL HOUSING LINER ATTACHMENT PARTS | \$ 84.00              |                    |
| 24                               | FRONT CAR PLATE NO.                        | S/N \$ 60.00          | <b>\$ 40.00</b>    |
| 25                               | <b>Added parts see attached</b>            | <b>\$ 264.00</b>      | <b>\$ 15.60</b>    |
| 26                               | SUNDRIES                                   | \$ 300.00             | <b>\$ 8.64</b>     |
| <b>TOTAL SPARE PARTS CHARGES</b> |                                            | <b>: \$ 12,581.00</b> | <b>\$ 3,237.84</b> |
| <b>TOTAL LABOUR CHARGES</b>      |                                            | <b>: \$ 4,752.00</b>  | <b>\$ 1,602.00</b> |
| <b>GRAND TOTAL</b>               |                                            | <b>: \$ 17,333.00</b> | <b>\$ 4,839.84</b> |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

## Supplementary Estimate 1

GST Reg No. 19-9902271-W

| <b>AIG Asia Pacific Insurance Pte Ltd</b><br>78 Shenton Way<br>#07-16 AIG Building<br>Singapore 079120<br><b>Attn: Mr. Adrian Ling - Motor Claims Dept</b><br><b>Tel: 6841 0055 - Fax: 6256 4315</b> |                  | <b>Estimate No.</b><br><b>Date</b><br><b>Service Advisor</b><br><b>Pages</b><br><b>Regn No</b><br><b>Model No</b> | PA/OD/0253/2020/GW<br>12-Mar-20<br>Glory Tan<br>1 of 1<br>SMA 8682 U<br>Audi A3 Sedan 1.0 TFSI |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|-------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------|
| Quantity                                                                                                                                                                                             | Description      | Unit Price                                                                                                        | Amount                                                                                         |
| <u>Parts</u>                                                                                                                                                                                         |                  |                                                                                                                   |                                                                                                |
| 1                                                                                                                                                                                                    | Air cond sticker | \$ 7.00                                                                                                           | \$ 5.36                                                                                        |
| 2                                                                                                                                                                                                    | Caution sticker  | \$ 13.00                                                                                                          | \$ 10.24                                                                                       |
| 3                                                                                                                                                                                                    | Noise insulation | \$ 244.00                                                                                                         |                                                                                                |
| TOTAL                                                                                                                                                                                                |                  | \$ 264.00                                                                                                         | \$ 15.60                                                                                       |

*For Premium Automobiles Pte Ltd*

\_\_\_\_\_  
Authorised Signature

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** :  
**Surveyed Date** :  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** :

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant