



TRANS EUROKARS PTE LTD



## ESTIMATE COST OF REPAIRS

|                                                                                                                                 |                                 |                                                                                                                         |                 |                                         |                            |
|---------------------------------------------------------------------------------------------------------------------------------|---------------------------------|-------------------------------------------------------------------------------------------------------------------------|-----------------|-----------------------------------------|----------------------------|
| INDIA INTERNATIONAL INSURANCE P/L<br>64 CECIL STREET<br>#04-#05 IOB BUILDING<br>SINGAPORE 049711<br>ATTN.: MOTOR CLAIMS<br>FAX: |                                 | NAME: Ms Khiew Siew Lan<br>ADDRESS: Blk 73 Telok Blangah Heights<br>#14-307<br>Singapore 100073<br>TEL: 97898186Josephi |                 | WIP: 64319<br>EXCESS:<br>DATE: 9-Mar-20 |                            |
| VEH NO:                                                                                                                         | SKX2192J                        | DATE IN:                                                                                                                |                 | CONTACT PERSON:                         | Eva 63310683               |
| CHASSIS NO:                                                                                                                     | JM6BM42A8G0323222               | MILEAGE:                                                                                                                |                 | TYPE OF CLAIM:                          | THIRD PARTY CLAIM          |
| MODEL:                                                                                                                          | MAZDA3                          | DATE REG.:                                                                                                              | 30-Nov-15       | POLICY NO.:                             |                            |
| NATURE OF WORKS                                                                                                                 |                                 |                                                                                                                         |                 |                                         |                            |
| Parts Description                                                                                                               |                                 |                                                                                                                         |                 |                                         |                            |
| NO                                                                                                                              | QTY                             |                                                                                                                         |                 | REVISED                                 | PRICES                     |
| 1                                                                                                                               | REAR BUMPER <i>de</i>           | 1                                                                                                                       | MBHN1-50-221ABB |                                         | \$ 1,128.60                |
| 2                                                                                                                               | BRACKET CENTER ? X SVC          | 1                                                                                                                       | MKD53-50-251    |                                         | \$ 5.40                    |
| 3                                                                                                                               | REAR REINFORCEMENT ? X SVC      | 1                                                                                                                       | MB45A-50-260    |                                         | \$ 564.20                  |
| 4                                                                                                                               | GROMMET, REAR BUMPER <i>ne</i>  | 4                                                                                                                       | MBHN1-50-0Z1A   |                                         | \$ 10.80                   |
| 5                                                                                                                               | GROMMET, REAR BUMPER <i>ne</i>  | 2                                                                                                                       | M9991-00-501    |                                         | \$ 6.00                    |
| 6                                                                                                                               | FASTENER, REAR BUMPER <i>ne</i> | 4                                                                                                                       | MB45A-56-146A   |                                         | \$ 12.00                   |
| 7                                                                                                                               | RIVET, REAR BUMPER <i>ne</i>    | 4                                                                                                                       | MBBM4-50-355    |                                         | \$ 18.00                   |
| 8                                                                                                                               | ORNAMENT, MAZDA                 | 1                                                                                                                       | MBHN1-51-721    |                                         | \$ 56.10                   |
| 9                                                                                                                               | MASCOT, REAR                    | 1                                                                                                                       | MBHN1-51-730    |                                         | \$ 78.20                   |
| 10                                                                                                                              | ORNAMENT, SKYACTIVE             | 1                                                                                                                       | MBHN1-51-771    |                                         | \$ 66.80                   |
| 11                                                                                                                              | FASTENER, BOOTLID               | 2                                                                                                                       | MEG21-51-146    |                                         | \$ 12.40                   |
| 12                                                                                                                              | GROMMET, BOOTLID                | 2                                                                                                                       | MGA7B-51-146    |                                         | \$ 6.60                    |
| 13                                                                                                                              | GASKET LHS, BOOTLID LAMP        | 1                                                                                                                       | MB45A-51-3J8    |                                         | \$ 22.00                   |
| 14                                                                                                                              | GASKET RHS, BOOTLID LAMP        | 1                                                                                                                       | MB45A-51-3H8    |                                         | \$ 22.00                   |
| 15                                                                                                                              | GASKET LHS, TAILLAMP <i>ne</i>  | 1                                                                                                                       | MBHN1-51-163    |                                         | \$ 22.00                   |
| 16                                                                                                                              | GASKET RHS, TAILLAMP <i>ne</i>  | 1                                                                                                                       | MBHN1-51-153    |                                         | \$ 22.00                   |
| TOTAL PARTS                                                                                                                     |                                 |                                                                                                                         |                 |                                         | \$ 2,053.10                |
| TOTAL PARTS COST                                                                                                                |                                 |                                                                                                                         |                 |                                         | \$ 2,053.10                |
| Labour Description                                                                                                              |                                 |                                                                                                                         |                 |                                         |                            |
| 1                                                                                                                               | MZ-BR-REAR02                    | TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO REPAIR BOOTLID AND ALL AREAS AFFECTED BY THE ACCIDENT.                |                 |                                         | 660 \$ <del>1,650.00</del> |
| 2                                                                                                                               | MZ-SP-SREAR3                    | TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND BOOT LID.                                                                |                 |                                         | 630 \$ <del>1,800.00</del> |
| 3                                                                                                                               | MZ-BR-PLATE1                    | TO SUPPLY NUMBER PLATE. X SVC                                                                                           |                 |                                         | NETT \$ <del>X</del> 70.00 |

|   |              |                                                    |      |                         |
|---|--------------|----------------------------------------------------|------|-------------------------|
| 4 | MZ-BR-REVS   | TO TRANSFER REVERSE SENSORS.                       | NETT | \$ 330.00               |
| 5 | MZ-BR-CAVITY | TO CARRY-OUT BODY CAVITY PRESERVATION. <b>X NN</b> | X    | \$ 250.00               |
| 6 | MZ-BR-ELECTR | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING. | 150  | \$ 250.00               |
| 7 | MZ-BR-REPROG | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.    | 180  | \$ 350.00               |
| 8 | MZ-BR-SUNDRI | SUNDRIES.                                          | NETT | \$ <sup>20</sup> 100.00 |

|                    |      |             |
|--------------------|------|-------------|
| TOTAL LABOUR       | \$ - | \$ 4,890.00 |
| TOTAL PARTS        | \$ - | \$ 2,053.10 |
| TOTAL              | \$ - | \$ 6,943.10 |
| LESS EXCESS        | \$ - | \$ -        |
| TOTAL AFTER EXCESS | \$ - |             |
| GST 7%             | \$ - | \$ -        |
| GRAND TOTAL        | \$ - | \$ -        |

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Rahul*  
4p 20010068  
3 days  
12/03/2020  
Resy before paint