

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722

Tel: (65) 6272 3892  
Fax: (65) 6270 8314

Co. Reg. 198904033G  
GST Reg. M2-0088864-2

Steve (LKK)

10/3/20, 3.00pm  
wrt PR  
dyi, P/P, Ry Bel RJ  
6

**Estimate**

09/03/2020

**MS FIRST CAPITAL INSURANCE LIMITED**

36 Robinson Road  
#16-01 City House  
Singapore 068877.

Attention :- XA026

Page # :- 1

Veh # :- SMK873K

Veh Model :- PEUGEOT 3008 TURBO 1.6

Estimate# :- CK420495

Claim # :-

ACC. Date :- 07/03/20

Terms :- C.O.D Days

Remarks :-

No. Description Qty U.Price Amounts S\$

**LIST ITEMS :**

1.	TAILLAMP ASSY RH <del>CRN</del> X NMI	1	PC	400.00	400.00 X
2.	TAILLAMP LOWER BRACKET RH / CRN	1	PC	140.00	140.00 /
3.	REAR BUMPER GARNISH - CENTER / BR	1	PC	520.00	520.00 1550 /
4.	REAR BUMPER GARNISH - RH / CRN	1	PC	480.00	480.00 /
5.	REAR BUMPER / BR	1	PC	980.00	980.00 /
6.	REAR BUMPER REFLECTOR RH / BR	1	PC	120.00	120.00 /
7.	REAR BUMPER SPONGE X NMI	1	PC	200.00	200.00 X
8.	REAR BUMPER REINFORCEMENT X NMI	1	PC	450.00	450.00 X
9.	REAR BUMPER BRACKET RH (Rubin) /	1	PC	145.00	145.00 /
10.	REAR BUMPER RETAINER RH / BR	1	PC	140.00	140.00 /
11.	REAR BUMPER CLIPS - MC	10	PCS	8.00	80.00 30 /
12.	REAR FENDER COWLING RH - TN	1	PC	160.00	160.00 /
13.	REAR END PANEL X R	1	PC	950.00	950.00 X
14.	REAR END PANEL TOP COVER X NMI	1	PC	380.00	380.00 X
15.	REAR FENDER INNER TRIM RH - CHECK X NMI	1	PC		
16.	TAILGATE (REPAIR) X R	1	PC		
17.	TAILGATE LOGO / MC	1	PC	120.00	120.00 /
18.	TAILGATE EMBLEM - PEUGEOT / MC	1	PC	115.00	115.00 /
19.	TAILGATE EMBLEM - 3008 / MC	1	PC	100.00	100.00 /

4080  
-10%  
3672

LIST TOTAL S\$

10 20% DISCOUNT S\$

~~Supplementary 1 pc rear stopper RH \$30~~

5,480.00

-1,096.00

4,384.00

**SPECIAL NET ITEMS :**

1.	REVERSE SENSOR / BR	1	SET	200.00	200.00 /
----	---------------------	---	-----	--------	----------

SPECIAL NET TOTAL S\$

200.00

**LABOUR :**

TO CUT/WELD REAR END PANEL. KNOCK AND STRAIGHTEN REAR FENDER RH, SPARE WHEEL PANEL. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION

P- 3672

M- 200

L- 1480

5352

600 900.00 700 /

600 700.00 /

SPRAY PAINT REAR FENDER LH, REAR END PANEL, REAR BUMPER, REAR BUMPER GARNISH, TAILGATE

REMOVE & REFIT LUGGAGE COMPARTMENT INNER TRIM, GARNISH, COVERING

50 / 60.00

REMOVE & REINSTALL REVERSE SENSOR AND CHECK FUNCTION

30 / 50.00

LABOUR TOTAL S\$

1,710.00

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: **(65) 6476 3333**  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722

Tel: **(65) 6272 3892**  
Fax: (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088864-2

# Estimate

09/03/2020

**MS FIRST CAPITAL INSURANCE LIMITED**  
36 Robinson Road  
#16-01 City House  
Singapore 068877.

Attention :- XA026

Page # :- 1 137786  
Veh # :- SMK873K  
Veh Model :- PEUGEOT 3008 TURBO 1.6  
Estimate# :- CK420495  
Claim # :-  
ACC. Date :- 07/03/20  
Terms :- C.O.D Days  
Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E



NON-TAX AMOUNT S

AMOUNT S\$ 6,294.00

GST @ 7 % 440.58

AMOUNT DUE S\$ 6,734.58

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: