



Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

ACTIV TECHNOLOGY PTE LTD

Estimate : ES006959

Attention : THE OWNER
 Contact : 96266726 98187189

Date : 09/03/2020
 Vehicle Num. : SLN17L
 Make/Model : BMW 740LI-2017
 Chassis/Eng# : WBA7E22080G764272/19389939B58F
 Accident Date : 08/03/2020
 Claim No. :
 Reference :
 Policy No. :

*Not withain
 Penny After Pain
 2 days*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :
 KNOCK OUT DENT ON L/H REAR DOOR, L/H REAR FENDER AND
 SPARY PAINT

800
 1,200.00

 1,200.00

Labour Total S\$:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

SingDollars : One Thousand Two Hundred Only

Total S\$: 1,200.00
 =====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun