

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBG3964M200309

**Estimate****Customer**

Page 01 -02

Name: QBE Insurance (International) Limited

Date: 11-03-20

Address Motor Claims Department

Vehicle No: GBG3964M

1 Raffles Quay #29-10

Model/Make: Fiat Dobl Cargo

South Tower

Singapore 048583

Maxi 1.6 MTJ AMT

| Item No.          | Descriptions Of Parts                          | Original Quotation / Estimation | Revised Quotation / Cost Of Repair |
|-------------------|------------------------------------------------|---------------------------------|------------------------------------|
| 1                 | Rear Bumper 734.34                             | \$ 745.00                       | ✓                                  |
| 2                 | Bumper Clips 1 set 50                          | \$ 65.00                        | ✓                                  |
| 3                 | Bumper Reinforcement 220.92                    | \$ 752.00                       | ✓                                  |
| 4                 | Bumper Bracket                                 | \$ 155.00                       | ✓                                  |
| 5                 | Bumper Reflector                               | \$ 117.60                       | ✓                                  |
| 6                 | Bumper Reverse Sensor                          | \$ 220.00                       | SN 200 S-N                         |
|                   | Tail Lamp 02 pcs (@ S\$462.70) 420.50          | \$ 925.40                       | 1 pc                               |
|                   | Floor Panel Garnish                            | \$ 1,379.80                     | ✓                                  |
| 7                 | Rear Lh Tailgate 2385.50                       | \$ 2,395.00                     | ✓                                  |
| 8                 | Tailgate Glass                                 | \$ 841.50                       | ✓                                  |
| 9                 | Tailgate Glass Sealant                         | \$ 80.00                        | SN 40 S-N                          |
| 10                | Tailgate Weatherstrip                          | \$ 344.50                       | ✓                                  |
| 11                | Tailgate Inner Trim Board                      | \$ 384.90                       | ✓                                  |
| 12                | Tailgate Inner Trim Board Clips 1 set          | \$ 164.50                       | ✓                                  |
| 13                | Tailgate Wiper Motor                           | \$ 428.00                       | ✓                                  |
| 14                | Tailgate Wiper Link ARM                        | \$ 165.30                       | ✓                                  |
| 15                | Tailgate Wiper Rubber                          | \$ 98.00                        | ✓                                  |
| 16                | Tailgate Hinge 02 pcs (@ S\$166.30)            | \$ 332.60                       | 1 pc                               |
| 17                | Tailgate Lock                                  | \$ 331.00                       | ✓                                  |
| 18                | Tailgate Outer Garnish                         | \$ 279.00                       | ✓                                  |
| 19                | Tailgate "70 KM/H" Sticker                     | \$ 15.00                        | SN 105.~                           |
| 20                | Tailgate "Doblo" Emblem 80.20                  | \$ 118.00                       | ✓                                  |
| 21                | Tailgate "Maxi" Emblem 62.10                   | \$ 86.00                        | ✓                                  |
| 22                | Tailgate Number Plate Lamp 02 pcs (@ S\$51.50) | \$ 103.00                       | ✓                                  |
| 23                | Tailgate Number Plate Outer Garnish            | \$ 154.40                       | ✓                                  |
| 24                | Tailgate Number Plate and Base                 | \$ 48.00                        | SN 405.~                           |
| 25                | Tail Lamp Panel                                | \$ 989.30                       | ✓                                  |
| 26                | Rear Rh Tailgate 1844.71                       | \$ 1,895.90                     | ✓                                  |
| 27                | Tailgate Weatherstrip                          | \$ 297.00                       | ✓                                  |
| 28                | Tailgate Lock Top                              | \$ 189.30                       | ✓                                  |
| 29                | Tailgate Lock Upper                            | \$ 192.90                       | ✓                                  |
| 30                | Tailgate Outer Garnish 186.45                  | \$ 321.80                       | ✓                                  |
| 31                | Tailgate "Professional" Emblem                 | \$ 163.50                       | ✓                                  |
| 32                | Tailgate Glass Sealant                         | \$ 80.00                        | SN 405.~                           |
| 33                | Tailgate "Fiat Logo" Emblem                    | \$ 87.80                        | ✓                                  |
| 34                | Tailgate Glass                                 | \$ 680.00                       | ✓                                  |
| 35                | Tailgate Glass Sealant                         | \$ 80.00                        | SN X                               |
| 36                | Tailgate "6 PAX" Sticker                       | \$ 15.00                        | SN 105.~                           |
| C/F Balance ----> |                                                | \$ 15,721.00                    |                                    |



M/s Liu's Brother Auto Engrg Wks

P-9014-62

10%

P-8113-15

S-N 340-00

L-1690-00

10143-15

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

RQB No: 53291793 | Tel: 6741-1730 / 731 | Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBG3964M200309

**Estimate**

Customer

Page 02 -02

Name: QBE Insurance (International) Limited

Date: 11-03-20

Address Motor Claims Department

Vehicle No: GBG3964M

1 Raffles Quay #29-10

Model/Make: Fiat Dobl Cargo

South Tower

Singapore 048583

Maxi 1.6 MTJ AMT

| Item No. | Descriptions Of Parts                                                  | Original Quotation / Estimation | Revised Quotation / Cost Of Repair |
|----------|------------------------------------------------------------------------|---------------------------------|------------------------------------|
|          | B/F Balance ---->                                                      | \$ 15,721.00                    |                                    |
|          | Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc   | \$ 1,000.00                     | 450                                |
|          | To putty & spray painting & including touch up paint on accident af    | \$ 1,000.00                     | 800                                |
|          | Remove & reinstall Rear Rh & Lh Windscreen Glass to facilitate repa    | \$ 240.00                       | 200                                |
|          | Remove and refix rear Rh & Lh tailgate components & wiper mechan       | \$ 180.00                       | 100                                |
|          | To check all wiring & electrical component for proper function         | \$ 80.00                        | 30                                 |
|          | Remove and refix rear reverse sensor                                   | \$ 100.00                       | 50                                 |
|          | To apply Rust Proofing , reseal tuff-coating treatment on accident are | \$ 80.00                        | 60                                 |

Total Parts &amp; Labour of estimate for damaged vehicle

\$ 49,843.00

1690

Total amount in Lump Sum Basis for repaired vehicle

SDLS: \_\_\_\_\_



M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_