

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 16 Mar 2020


SUPPLEMENTARY FOR REPAIR: HONDA NM4-02 ABS - FBJ8060Y

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Left side skirting (Gloss black)	\$275.00 / CRK
1 pc	Left rear signal assy	\$195.00 / SCR
1 pc	Left rear signal cover	\$214.00 / CRK
1 pc	Radiator assy	\$880.00 / DEF
1 pc	Left aluminium cover	\$275.00 / DEF
1 pc	Engine cover left	\$245.00 / CRK
1 pc	Front left signal	\$195.00 / CRK
1 pc	Front left signal upper cover	\$190.00 / CRK
1 pc	Left box side cover lower	\$175.00 / DEF
1 pc	Rear centre cover	\$235.00 / CRK
1 pc	Left upper fairing	\$485.00 / MMS CRK
1 pc	Front left fairing	\$395.00 / MMS
1 pc	Center left fairing	\$295.00 / MMS
1 pc	Hand brake bracket	\$235.00 / BT
1 pc	RIGHT UPPER FAIRING	\$485.00 / CRK
	Less discount 10%	\$4,289.00
		\$428.90
		\$3,860.10
<u>Special nett items</u>		
1 pc	Coolant	\$50.00 / NEC
1 pc	TRP IN	\$157 / CRK
1)	Welding	\$150.00 50
Total Estimate		<u>\$4,060.10</u>

Note: The above estimate is subjected to the prevailing GST of 7%



 For Bike Production Pte Ltd