

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Mar 2020 Sendback Est	12 Mar 2020 15:36 \$130.00	13 Mar 2020 10:09 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: SWIFT GREEN LIMOUSINE , Co. Reg. No.: 53248186X									
Vehicle Reg. No.: SMP8960M		Date of Loss: 12/03/2020 08:00 - :59 [118 Months and 15 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM20D201272/SMP8960M/PAULINE		Policy/Cover Note No.: DMHCSNW00000441900 (Comprehensive)							
		Excess: \$1,250.00							
Repairer: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Pauline Tham]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 24/03/2020]									
Driver/Custodian: SHAFRUDIN BIN ROWDEN (65 / Male) , NRIC: S0099573H, Tel: +6592203673 Email: NOEMAIL									
Adj Asg. Remarks: fire case. 1. Please conduct investigation. 2. Check on last servicing date of vehicle. 3. Please let us have SCDF report. 4. Please let us have the market value. sect I - excess \$1250									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
CHINA_TAIPIING (27/03/2020): Alert - Adj Mandate Approved (\$0.00) - SMP8960M - Claim Handler: Pauline Tham									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SMP8960M (SNM20D201272/SMP8960M/PAULINE)

OD

Mar 12 2020 8:00AM

[SWIFT GREEN LIMOUSINE]

Cheng Hoe Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)
▼

Assessment Reports

1 per page ▼
 ☒

No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	12/03/20 15:36	Repairer Estimates		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/03/20 14:11	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page ▼
 ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/03/20 18:07	General View		Load JPG	☒
2	16/03/20 18:07	General View		Load JPG	☒
3	16/03/20 18:07	General View		Load JPG	☒
4	16/03/20 18:07	General View		Load JPG	☒
5	16/03/20 18:07	General View		Load JPG	☒
6	16/03/20 18:07	General View		Load JPG	☒
7	16/03/20 18:07	General View		Load JPG	☒
8	16/03/20 18:07	General View		Load JPG	☒
9	16/03/20 18:07	General View		Load JPG	☒
10	16/03/20 18:07	General View		Load JPG	☒
11	16/03/20 18:07	General View		Load JPG	☒
12	16/03/20 18:07	General View		Load JPG	☒
13	16/03/20 18:07	General View		Load JPG	☒
14	16/03/20 18:07	General View		Load JPG	☒
15	16/03/20 18:07	General View		Load JPG	☒
16	16/03/20 18:07	General View		Load JPG	☒
17	16/03/20 18:07	General View		Load JPG	☒
18	16/03/20 18:07	General View		Load JPG	☒
19	16/03/20 18:07	General View		Load JPG	☒
20	16/03/20 18:07	General View		Load JPG	☒
21	16/03/20 18:07	General View		Load JPG	☒
22	16/03/20 18:07	General View		Load JPG	☒
23	16/03/20 18:07	General View		Load JPG	☒
24	16/03/20 18:07	General View		Load JPG	☒
25	16/03/20 18:07	General View		Load JPG	☒
26	16/03/20 18:07	General View		Load JPG	☒
27	16/03/20 18:07	General View		Load JPG	☒
28	16/03/20 18:07	General View		Load JPG	☒
29	16/03/20 18:07	General View		Load JPG	☒
30	16/03/20 18:07	General View		Load JPG	☒
31	16/03/20 18:07	General View		Load JPG	☒
32	16/03/20 18:07	General View		Load JPG	☒
33	16/03/20 18:07	General View		Load JPG	☒
34	16/03/20 18:07	General View		Load JPG	☒
35	16/03/20 18:07	General View		Load JPG	☒
36	16/03/20 18:07	General View		Load JPG	☒
37	16/03/20 18:07	General View		Load JPG	☒

Assessment Reports				1 per page ▼	✓
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
38	16/03/20 18:07	General View		Load JPG	✓
39	16/03/20 18:07	General View		Load JPG	✓
40	16/03/20 18:07	General View		Load JPG	✓
41	16/03/20 18:07	General View		Load JPG	✓
42	16/03/20 18:07	General View		Load JPG	✓
43	16/03/20 18:07	General View		Load JPG	✓
44	16/03/20 18:07	General View		Load JPG	✓
Documentation				1 per page ▼	✓
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	12/03/20 15:36	TOWING FEE		Load JPG	✓
2	03/04/20 13:37	TOWING TAX INVOICE		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/05/20 11:04	LTA REBATE		Load PDF	
2	18/05/20 11:06	INVESTIGATION REPORT		Load PDF	
3	18/05/20 11:23	SCDF FIRE REPORT INVOICE		Load PDF	
4	18/05/20 11:44	LETTER		Load PDF	

Linked Accident Report Documents

Assessment Reports				View	View in Browser ▼
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		1 per page ▼	✓
1	12/03/20 15:25	Accident Statement		Load HTM	
Photos/Images				3 per page ▼	✓
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	12/03/20 15:25	Identification Card		Load JPG	✓
2	12/03/20 15:25	Identification Card		Load JPG	✓
3	12/03/20 15:25	ACRA1		Load JPG	✓
4	12/03/20 15:25	ACRA2		Load JPG	✓
5	12/03/20 15:25	Driving License		Load JPG	✓
6	12/03/20 15:25	Accident Photo		Load JPG	✓
7	12/03/20 15:25	Accident Photo		Load JPG	✓
8	12/03/20 15:25	Accident Photo		Load JPG	✓
9	12/03/20 15:25	Accident Photo		Load JPG	✓
10	12/03/20 15:25	Accident Photo		Load JPG	✓
11	12/03/20 15:25	Accident Photo		Load JPG	✓
12	12/03/20 15:25	Accident Photo		Load JPG	✓
13	12/03/20 15:25	SCENE PHOTO		Load JPG	✓
Documentation				1 per page ▼	✓
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	12/03/20 15:23	Sketch Plan		Load JPG	✓
2	12/03/20 15:23	Sketch Plan #2		Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS4/CTI20003978/NTD3S2**Date:** 18/05/2020**REFERENCE**

Insured/Claimant:	SWIFT GREEN LIMOUSINE	Policy No:	DMHCSNW00000441900		
Date of Loss:	12/03/2020	Nature of Claim:	OD	Claim No:	SNM20D201272/SMP8960M/PAULINE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP8960M	Engine No:	27186030026341
Make & Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Chassis No:	WDD2120472A158587
Reg. Date:	26/04/2010 (Man. Year: 2009)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	S\$75,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R17	Rear Tyre Size:	245/45 R17
Front Left Side:	Habilead 5 mm	Rear Left Side:	Habilead 5 mm
Front Right Side:	Habilead 5 mm	Rear Right Side:	Habilead 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	130.00	0.00	130.00	100.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	130.00	0.00	130.00	100.00
- Excess (S\$)	0.00	1,250.00	-1,250.00	
(S\$)	130.00	-1,250.00	1,380.00	1,061.54
+ GST 7.00/7.00% (S\$)	9.10	0.00	9.10	100.00
Nett Amount (S\$)	139.10	-1,250.00	1,389.10	998.63

INSPECTION

Date of Assignment:	13/03/2020 Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	13/03/2020 Inspected At:	BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #01-04 SINGAPORE 159723
Estimated Period of Repair:	0.0 days	Repairer: Cheng Hoe Motor Pte Ltd (Yishun)

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$75,000.00
OMV :	\$55,078.00
PARF Rebate (1) :	\$27,539.00
Quota Premium Paid :	\$39,563.00
COE Rebate (2) :	\$36,457.00
Total Rebate (1) + (2) = :	\$63,996.00

The total amount incurred will be Market Value \$75,000.00 minus Total Rebate \$63,996.00 = \$11,004.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 May 2020)
Parts:	143	MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP8960M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING (BY KING DOLLY) - BILL ATTACH	New	130.00	0.00
Gross Labour Cost (\$\$)			130.00	0.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >