

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Mar 2020 Edit Reg		13 Mar 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	NG HAN TONG , Co. Reg. No.: -		
Main Claimant:	WENDY WONG SWEE LIAN , ID: S7725160Z		
Vehicle Reg. No.:	SJG6702M	Date of Loss:	08/01/2020 00:00 - :59 [28 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 6506928042SG	Policy/Cover Note No.:	1800004539
Vehicle Reg. No. (Insured):	SKA758L	Policy No. (Claimant):	170004501-02
		Excess:	
Repairer:	Team Auto Pro Pte Ltd - Sin Ming (HQ) 160 Sin Ming Drive #01-14 Sin Ming Autocity, 575722 Sin Ming - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 25/03/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG (05/05/2020): **Re: No OI GIA Report - SKA758L**
- AIG_SG (17/03/2020): **No OI GIA Report**

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJG6702M (6506928042SG)
[SKA758L]**

TP

WENDY WONG SWEE LIAN

Jan 8 2020 12:00AM

[NG HAN TONG]

Team Auto Pro Pte Ltd - Sin Ming

View

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/05/20 16:44	Before Repair Photo	Load JPG	<input checked="" type="checkbox"/>
2	05/05/20 16:44	Before Repair Photo	Load JPG	<input checked="" type="checkbox"/>
3	05/05/20 16:44	Before Repair Photo	Load JPG	<input checked="" type="checkbox"/>
4	05/05/20 16:44	Before Repair Photo	Load JPG	<input checked="" type="checkbox"/>
5	05/05/20 16:44	Before Repair Photo	Load JPG	<input checked="" type="checkbox"/>
6	05/05/20 16:44	Before Repair Photo	Load JPG	<input checked="" type="checkbox"/>
7	05/05/20 16:44	Before Repair Photo	Load JPG	<input checked="" type="checkbox"/>
8	05/05/20 16:44	Before Repair Photo	Load JPG	<input checked="" type="checkbox"/>
9	05/05/20 16:44	Before Repair Photo	Load JPG	<input checked="" type="checkbox"/>
10	05/05/20 16:44	Before Repair Photo	Load JPG	<input checked="" type="checkbox"/>
11	05/05/20 16:44	Before Repair Photo	Load JPG	<input checked="" type="checkbox"/>
12	05/05/20 16:44	Before Repair Photo	Load JPG	<input checked="" type="checkbox"/>
13	05/05/20 16:44	Before Repair Photo	Load JPG	<input checked="" type="checkbox"/>
14	05/05/20 16:44	Before Repair Photo	Load JPG	<input checked="" type="checkbox"/>
15	05/05/20 16:44	Before Repair Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/03/20 14:15	ACKNOWLEDGEMENT EMAIL TO AIG DD 13.03.2020	Load PDF	
2	16/03/20 14:15	EMAIL FROM AIG DD 13.03.2020	Load PDF	
3	16/03/20 14:15	NOTIFICATION FROM WORKSHOP + TP GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG20004019/BHA3S2**Date:** 13/05/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800004539
Claimant Vehicle No :	SJG6702M	Insured Vehicle No :	SKA758L
Date of Loss:	08/01/2020	Nature of Claim:	TP
		Claim No:	6506928042SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJG6702M		
Make & Model:	TOYOTA C-HR HYBRID, 1.8 E G CVT (A)	Engine No:	2ZR8164737
Reg. Date:	31/08/2017 (Man. Year: 2017)	Chassis No:	ZYX102063005
Colour:	Silver	Odometer:	32755 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	13/03/2020		
Date Inspected:	16/03/2020	Inspected At:	Team Auto Pro Pte Ltd - Sin Ming (HQ) 160 Sin Ming Drive #01-14 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	3.0 days		

Adjuster: Lim Teow Guan**Manager:** VIC ALPEH*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER TOW COVER	Dislodged	0.00 F	*- F	
2	1		*REAR BUMPER LOWER SPOILER	Cut	0.00 F	*- F	
					Total Parts (\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >