

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

GST:201004495R RCB NO:201004495R

M/S : MSIG INSURANCE

Estimate No: M001027

Date: 16-Mar-20

Veh Reg No: SMJ8603B

Make/Model: NISSAN QASHQAI 2.0

Chassis No: SJNFBAJ11U1916191

Engine No: MR20453000W

Reg. Date : 06/03/2017

ATTN: Motor Claim Department

Your Ref No: **SMJ8603B**

Claim Type: Third Party

Accident Date: 12/03/2020

Estimate Repair Cost to Vehicle No : SMJ8603B

PAGE:1/2

S/N	Description	Quantity	Unit	Price	Amount
	<u>NETT PRICE</u>			<u>S\$</u>	<u>S\$</u>
1	Rear Bumper / De .	1	PCS	796.70	796.70 717
2	Rear Bumper Side Retainer - RH X NN	1	PCS	55.10	55.10 X
3	Rear Fender Dust Cover - RH X	1	PCS	99.10	99.10 X
4	Rear Fender Protector - RH / Scr .	1	PCS	654.00	654.00 483
5	Rear Door - RH / Blue	1	PCS	1166.20	1166.20 1104.8
6	Rear Door Lock - RH X NN	1	PCS	172.30	172.30 X
7	Rear Door Protector - RH / Scr	1	PCS	280.40	280.40 188.9
8	Rear Door Rubber X	1	PCS	189.80	189.80 X
9	Rear Upper Arm - RH X NN	1	PCS	266.40	266.40 X
10	Rear Knuckle Arm - RH / BT - photo .	1	PCS	1322.80	1322.80 581.3
11	Rear Lower Arm - RH / BT - photo .	1	PCS	167.60	167.60
TOTAL				5170.40	5170.40
LESS 10%				4653.36	4653.36

SPECIAL NETT PRICE

12	Rear Tyre - RH / TN	1	PCS	280.00	280.00 140
13	Rear Sport Rim - (RAVS) / Cut	1	PCS	1200.00	1200.00 800.
14	Rear Shock Absorber - RH / BT - photo	1	PCS	172.20	172.20 150
15	Rear Hub Bearing - RH / BT - photo	1	PCS	350.70	350.70 300
TOTAL				2002.90	2002.90

3242.6
10%: 2918.34

1390

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

GST:201004495R RCB NO:201004495R

M/S : MSIG INSURANCE

Estimate No: M001027

Date: 16-Mar-20

Veh Reg No: SMJ8603B

ATTN: Motor Claim Department

Make/Model: NISSAN QASHQAI 2.0

Your Ref No: SMJ8603B

Chassis No: SJNFBAJ11U1916191

Claim Type: Third Party

Engine No: MR20453000W

Accident Date: 12/03/2020

Reg. Date : 06/03/2017

Estimate Repair Cost to Vehicle No : SMJ8603B

PAGE:2/2

S/N	Description	Quantity	Unit	Price	Amount
LABOUR CHARGES				SS	SS
16	Panel Beating				850.00 400
17	Rust Proofing				60.00 x NV
18	Towing (King Roller)				100.00 80
19	Alignment				100.00 60
20	To Remove & Replace Rear Under Carriage				280.00 150
21	To Remove & Replace Door Assy				80.00 40
22	To Spray Paint				820.00 400
				TOTAL	2290.00

5 Days.

Unpainted repair.

After repair photos.

Caro Qian - 82880282

Caro Qian - 82880282

16/3/2020.

5438.34

20% 4350

OVERALL TOTAL 8946.26

LKK Auto Consultants hence notify the Repairer of the following:

FOR FOCUS AUTO PTE LTD

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

AUTHORISE SIGNATURE