

E M SOLUTION PT

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722

Tel: 64560226

Fax: 64584500

Registration No: 201016308K

Shi Xingrui

16.03.2020

REPAIR ESTIMATE FOR TOYOTA CAMRY - SJU 6100 B

Not within 11 Sep 2000
Returning After Paint

- 1 pc. rear bumper fascia *532.50*
- 2 pcs. rear bumper reflectors
- 2 pcs. rear bumper side retainers
- 1 pc. rear bumper reinforcement
- 2 pcs. rear bumper brackets
- 1 pc. boot lid
- 1 pc. boot lid "Camry" badge
- 1 pc. boot lid "2.0" badge
- 1 pc. boot lid emblem
- 1 pc. boot lid outer garnish
- 1 pc. boot lid inner lock
- 1 pc. boot lid rubber
- 2 pcs. tail lamps assy *474.10* *015m x*
- 1 pc. rear end panel
- 1 pc. rear end panel top garnish
- 1 pc. rear exhaust silencer
- 2 pcs. rear exhaust mountings

<i>86.50</i>	<i>892.20</i>	
<i>32.90</i>	<i>173.00</i>	<i>x</i>
	<i>65.80</i>	<i>+</i>
	<i>397.80</i>	<i>?</i>
<i>87.60</i>	<i>175.20</i>	<i>x</i>
	<i>957.00</i>	<i>x</i>
	<i>48.65</i>	<i>—</i>
	<i>42.50</i>	<i>—</i>
	<i>58.50</i>	<i>—</i>
	<i>358.50</i>	<i>x</i>
	<i>591.30</i>	<i>x</i>
	<i>231.40</i>	<i>x</i>
<i>572.80</i>	<i>1,145.60</i>	<i>+</i>
	<i>639.30</i>	<i>x</i>
	<i>434.25</i>	<i>x</i>
	<i>952.10</i>	<i>x</i>
<i>48.50</i>	<i>97.00</i>	<i>x</i>
	<i>6,211.00</i>	
Less 25%	<i>1,552.75</i>	
	<i>4,658.25</i>	

- 1 set. rear bumper clips
- 1 set. rear end panel top garnish clips
- 1 set. reverse sensors

<i>45.00</i>	<i>SN</i>	<i>—</i>
<i>25.00</i>	<i>SN</i>	<i>x</i>
<i>270.00</i>	<i>SN</i>	<i>2000m</i>

- 1) Check electrical wirings.
- 2) Renew rear exhaust silencer
- 3) Repair accident damages and renew above parts.
- 4) Spray paint on accident affected portions.
- 5) Renew reverse sensors
- 6) Rust proofing on accident affected portions.

<i>60.00</i>	<i>201</i>
<i>80.00</i>	<i>x</i>
<i>980.00</i>	<i>440d</i>
<i>980.00</i>	<i>600d</i>
<i>80.00</i>	<i>501</i>
<i>80.00</i>	<i>x</i>

\$ 7,258.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: