



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20004040/Dbas2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 21-08-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3466D	Veh. Inspected	SH 9922M
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20001455MFSH	Excess (\$)	0.00
Assign From	KAREN TAN	Assign Date	16/03/2020

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHC851CVKU134195	Colour	BLUE
Odometer	148079	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	DAVANTI	5 mm
L/H Front Tyre	195/65 R15	DAVANTI	5 mm
R/H Rear Tyre	195/65 R15	DAVANTI	5 mm
L/H Rear Tyre	195/65 R15	DAVANTI	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION, N/S BODY AND N/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/03/2020	Inspection Date	16/03/2020
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **9 Working Days**