

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

12/03/2020

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

Attention :- XA026

WM PUL 16/3/20, 2.15pm
9 days
L/S
Ry AL

Page # :- 1
Veh # :- SGS7277P
Veh Model :- HONDA ACCORD
Estimate# :- CK420520
Claim # :-
ACC. Date :- 09/03/20
Terms :- C.O.D Days
Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1.	REAR BUMPER / DR	1	PC	995.00	995.00	✓
2.	REAR BUMPER BRACKET X NN	2	PCS	65.00	130.00	X
3.	REAR BUMPER REFLECTOR LAMP / DR	1-2	PCS	160.00	320.00	62 ✓
4.	REAR BUMPER SIDE RETAINER / DR	2	PCS	90.00	180.00	✓
5.	REAR BUMPER CLIPS / APC	10	PCS	5.00	50.00	✓
6.	BOOTLID / DR	1	PC	1,650.00	1,650.00	892 ✓
7.	BOOTLID LOCK / DT	1	PC	280.00	280.00	✓
8.	BOOTLID LOGO / MC	1	PC	55.00	55.00	✓
9.	BOOTLID REFLECTOR LAMP (RH) - CUT	1-2	PCS	330.00	660.00	330 ✓
10.	BOOTLID RUBBER / CRV	1	PC	310.00	310.00	168 ✓
11.	TAILLAMP (RH) / DR (LH) ? X NN	1-2	PCS	535.00	1,070.00	535 ✓
12.	END PANEL GARNISH / CRV	1	PC	160.00	160.00	✓
13.	END PANEL ASSY / DR	1	PC	789.00	789.00	575 ✓
14.	TAILLAMP BOTTOM BRACKET / DR	1-2	PCS	35.00	70.00	35 ✓
15.	SPARE TYRE BOARD X NN	1	PC	450.00	450.00	X
16.	REAR FENDER INNER SHIELD / TN	2	PCS	70.00	140.00	✓
17.	REAR EXHAUST / DR	2	PCS	750.00	1,500.00	✓
18.	REAR EXHAUST MOUNTING / TN	3-4	PCS	30.00	120.00	90 ✓
19.	REAR EXHAUST CHROME PIPE / DT	1-2	PCS	160.00	320.00	160 ✓
20.	REAR UNDER COVER / CRV	1	PC	430.00	430.00	✓

LIST TOTAL S\$

9,679.00

20% DISCOUNT S\$

-1,935.80

7,743.20

SPECIAL NET ITEMS :

1.	REAR BUMPER BODY KIT / DR	1	PC	500.00	500.00	400 ✓
2.	REAR PARKING SENSOR / DR	1	SET	200.00	200.00	✓
3.	REAR NUMBER PLATE X NN	1	PC	50.00	50.00	

SPECIAL NET TOTAL S\$

750.00

LABOUR :

TO INSPECT REAR LIGHTING WATER & LEAKAGE TEST

70 40.00

TO REMOVE & INSTALL REAR COMPARTMENT GARNISH,
CARPET, & ETC, IN ORDER TO CUT OFF END PANEL,
STRAIGHTEN FLOOR PANEL

1850

80 250.00

TO REMOVE & INSTALL REAR EXHAUST

80.00 ✓

TO CUT OFF END PANEL, STRAIGHTEN FLOOR PANEL,
AFFECTED AREAS AND RENEW DAMAGED PARTS

P - 5293.60
N - 600
L - 1850
7743.60

800 1,200.00

TO APPLY BODY JOINT SEALANT ON CUTTING AREAS

30 60.00

TO APPLY RUST PROOF ON AFFECTED AREAS

L/S - 6194.88
= 6200

30 60.00

TO SPRAY PAINT ON REPLACED, REPAIRED AREAS

Repair Limit \$5300

800 1,000.00

Estimate

12/03/2020

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

Page # :- 1 137821

Veh # :- SGS7277P

Veh Model :- HONDA ACCORD

Estimate# :- CK420520

Claim # :-

ACC. Date :- 09/03/20

Terms :- C.O.D Days

Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: **(65) 6476 3333**
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: **(65) 6272 3892**
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Attention :- **XA026**

No.	Description	Qty	U.Price	Amounts S\$
	LABOUR TOTAL S\$			2,690.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 11,183.20

GST @ 7 % 782.82

AMOUNT DUE S\$ 11,966.02

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: