



20 MAY 2020

Your Ref : GBJ6227Y  
Our Ref : TP/11528/FBN1758T/GBJ6227Y

**BY FAX & HAND**

India International Insurance Pte Ltd  
64 Cecil Street  
#04-00 & 06-00 IOB Building  
Singapore 049711

**ATTN: Mr. Derrick**

Dear Derrick,

**Accident Involving FBN1758T & GBJ6227Y on 07/03/2020**

We refer to the above-mentioned matter.

As instructed by our client, we proceed to quantify our claim as itemized below:

1. Cost of Repair (Inc 7% GST)	\$1,957.35
2. Loss of Use (4 days x \$20)	\$ 80.00
3. LTA Vehicle Insurance Search Fee	\$ 7.45
<b>TOTAL</b>	<b><u>\$2,044.80</u></b>

We attached our Tax Invoice and LTA Vehicle Insurer Search for your perusal.

Please acknowledge receipt.

If you require any further clarification, please do not hesitate to contact Mr Raymond at 6281 6520 ext. 220.

Thank you.

**BAN HOCK HIN CO PTE LTD**

.....  
Raymond Tan  
Manager/Insurance Dept  
Tel : 6281 6520 ext. 220  
Fax : 6284 2969  
Email : [raymond@bhh.com.sg](mailto:raymond@bhh.com.sg)





**TAX INVOICE**

Customer :  
INDIA INTERNATIONAL INSURANCE P.L.  
64 CECIL STREET  
#04-00 & #06-00  
IOB BUILDING  
SINGAPORE 049711  
MOTOR CLAIMS DEPT

GST Reg No. : M2-0010542-7

Invoice No. : **LECR20038024-I11528**  
Invoice Date : 17/04/2020  
Payment Due Date : 17/05/2020

CLAIM NO. : 11528  
POLICY NO. : AVFMSB0000651901  
VEHICLE NO. : FBN1758T  
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	SPRAY PAINT COVER SIDE REAR LH (LACQUER)	Spray	1	\$45.00	\$45.00
2	TRANSPORT CHARGES	Supply/Install	1	\$35.00	\$35.00
3	LABOUR	Supply/Install	1	\$260.00	\$260.00
4	SPRAY PAINT COVER SIDE REAR RH (LACQUER)	Spray	1	\$45.00	\$45.00
5	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT	REPLACE	1	\$222.00	\$199.80
				Disc %: 10%	
6	BRACKET BOX REAR (GIVI)	REPLACE	1	\$62.00	\$55.80
				Disc %: 10%	
7	COVER CLUTCH OUTER	REPLACE	1	\$28.00	\$25.20
				Disc %: 10%	
8	COVER SIDE REAR LH (WHITE)	REPLACE	1	\$40.00	\$36.00
				Disc %: 10%	
9	COVER SIDE REAR RH (WHITE)	REPLACE	1	\$40.00	\$36.00
				Disc %: 10%	
10	ENGINE BRACKET COMP	REPLACE	1	\$70.00	\$63.00
				Disc %: 10%	
11	MUDGUARD REAR	REPLACE	1	\$47.00	\$42.30
				Disc %: 10%	
12	PIPE EXHAUST ASSY	REPLACE	1	\$407.00	\$366.30
				Disc %: 10%	
13	PROTECTOR EXHAUST	REPLACE	1	\$38.00	\$34.20
				Disc %: 10%	
14	STICKER (CERTIS CISCO) SIDE REAR RH NEW MODEL	REPLACE	1	\$44.00	\$44.00
15	STICKER (CERTISCISCO) NEW LOGO	REPLACE	2	\$44.00	\$88.00
16	STICKER (CISCO) SIDE REAR LH NEW MODEL	REPLACE	1	\$15.00	\$15.00
17	BELLY PAN	Replace	1	\$34.00	\$30.60
				Disc %: 10%	
18	BOARD FOOTREST LH	Replace	1	\$52.00	\$46.80
				Disc %: 10%	
19	BOARD FOOTREST RH	Replace	1	\$52.00	\$46.80
				Disc %: 10%	



S/N	Description	Action	Qty	Unit Price	Amount
20	COVER RADIATOR	Replace	1	\$12.00	\$10.80
				Disc %: 10%	
21	COVER SIDE CENTRE RH (WHITE)	Replace	1	\$30.00	\$27.00
				Disc %: 10%	
22	LAMP SIGNAL FRONT LH	Replace	1	\$35.00	\$31.50
				Disc %: 10%	
23	LEVER BRAKE LH	Replace	1	\$18.00	\$16.20
				Disc %: 10%	
24	LEVER BRAKE RH	Replace	1	\$18.00	\$16.20
				Disc %: 10%	
25	MUDGUARD FRONT (WHITE)	Replace	1	\$52.00	\$46.80
				Disc %: 10%	
26	RIVET	Replace	7	\$2.00	\$12.60
				Disc %: 10%	
27	COVER SIDE CENTRE LH (WHITE)	Replace	1	\$30.00	\$27.00
				Disc %: 10%	
28	STAND MAIN	Replace	1	\$66.00	\$59.40
				Disc %: 10%	
29	SPRAY PAINT MUDGUARD FRONT (LACQUER)	Spray	1	\$30.00	\$30.00
30	STICKER (CISCO) MUDGUARD FRONT	Replace	1	\$37.00	\$37.00
SUB TOTAL					\$1,829.30
GST @ 7 %					\$128.05
<b>GRAND TOTAL (SGD)</b>					<b>\$1,957.35</b>

Validity: 30 days

For & on Behalf of  
**BAN HOCK HIN CO PTE LTD**

*[Handwritten Signature]*  


Printed by : RAYMOND

*bizSAFE<sub>3</sub>*



Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 13 Mar 2020 / 16:21:42

Receipt Date/Time : 13 Mar 2020 / 16:21:42

**Tax Invoice/Receipt**

Receipt No. : ITNET-00000-200313-002487

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - GBJ6227Y As at 07 Mar 2020/12:30:00 Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - GBJ6227Y Enquiry Fee 20200313161921638961	7.00	0.49	7.49
<b>Sub-Total</b>		7.00	0.49	7.49
<b>Total Before Rounding</b>		7.00	0.49	7.49
<b>Rounding Difference</b>				0.04
<b>Total Amount Payable</b>				7.45
Paid By				
	20200313162022172	Direct Debit: eNETS Debit (Internet Banking)		7.45
<b>Total</b>				7.45
<b>Cash Change</b>				0.00
<b>Tendered Amount</b>				7.45
<b>Excess Refundable Amount</b>				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



INDIA INTERNATIONAL INSURANCE PTE LTD  
 Co. Reg. No. 198703792k | GST Reg. No. M2-0078806-X  
 64 | Cecil Street | #04 | #05 | #06-02 | IOB Building | Singapore 049711  
 Office (65) 63476100 Email insure@iii.com.sg  
 Fax (65) 62244174 Website www.iii.com.sg

## EXPRESS SETTLEMENT

### DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MFL2020D0000615  
 Claimant Ref : FBN1758T

We/I, Ban Hock Hin Co. Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 2,000.00 (Global Sum) (repair cost), S\$                      (loss of essential), S\$                      (search fee), vehicle no. FBN1758T that was damaged pursuant to the accident which occurred on 07/03/2020 (date) at JUNCTION OF HOUGANG AVE 3 AND TAMPINES ROAD (location) involving vehicle no. GBJ6227Y (insured vehicle). This is pursuant to the inspection conducted on 16/03/2020 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner BAN HOCK HIN COMPANY PTE LTD ("the third party claimant") of vehicle no. FBN1758T to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to FBN1758T (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 2,000.00 to Ban Hock Hin Co. Pte Ltd.

Dated this 28th day of July, 2020

CLAIMANT:

Signature: [Signature]  
 Name: Tan Teck Hang  
 NRIC: S1438567C  
 Address: 6 Defu Lane 4  
Singapore 539410  
 Nationality: Singaporean  
 Occupation: Director



WITNESS:

Signature: [Signature]  
 Name: LKK Auto Consultants Pte Ltd  
 NRIC: 199607198R  
 Address: 51 Ubi Avenue 1  
#01-25 Paya Ubi Ind. Park S(408933)  
 Nationality:                       
 Occupation:                     

