



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Ref: CS/INC20004113/T1vd3e2

Date: 05-06-2020



ATTN: CHRYLLIS QUAH

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJK 464T	Veh. Inspected	SGM 8879C
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1088415-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	17/03/2020

2. Vehicle Particulars & Condition

Make & Model	MAZDA RX-8	c.c	1308
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	SE3P302628	Colour	BLACK
Odometer	137858 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/30 R19	YOKOHAMA	6 mm
L/H Front Tyre	185/30 R19	YOKOHAMA	6 mm
R/H Rear Tyre	185/30 R19	YOKOHAMA	6 mm
L/H Rear Tyre	185/30 R19	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	16/03/2020	Inspect Date / Time	17/03/2020 (04:41 PM)
Survey held at	RICO 60 AUTO SERVICES PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------