

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
MS FIRST CAPITAL INSURANCE LTD			Ref: CS3/FCI200	04128/Kqf3e2	
36 ROBINSON ROAD #16-01 CITY HOUSE INGAPORE 068877			Date: 11-08-2020		
			Code: FCI2		
1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHC 8790P	Veh. Inspected	WD 22T	
	Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
	Claim No.	D20001478MFSH	Excess (\$)	0.00	
	Assign From	MAY CHUA	Assign Date	16/03/2020	
2. Vehicle Particulars & Condition					
	Make & Model	ISUZU CYH52S	c.c	15681	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	JALCYH52SF7000061	Colour	WHITE / BLUE	
	Odometer	110911 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	295/80 R22.5 (D)	AVANTE	3/8 mm	
	L/H Front Tyre	295/80 R22.5 (D)	BRIDGESTONE	3/8 mm	
	R/H Rear Tyre	295/80 R22.5 (D/D)	AVANTE	4/4/7/7 mm	
	L/H Rear Tyre	295/80 R22.5 (D/D)	AVANTE	4/4/7/7 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.				
5.	5. General Information				
	Accident Date	13/03/2020	Inspect Date / Tim	<b>e</b> 05/08/2020 ( 12:09 PM )	
	Survey held at	160 SIN MING DRIVE #06-01			
	Repairer	MULTILATERAL SERVICES			
5a.	5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$70,000.00				

Report Ref No. CS3/FCI20004128/Kqf3e2

Inspected By

KONG SENG CHEONG

**Licensed Appraiser** 

K.K.LAU CPT(RET)

\_\_\_\_\_

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.