

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 08 Apr 2020

Preliminary Advice

Vehicle No	: SLU183C	Accident Date	: 14/03/2020
Make	: AUDI A3	Policy No.	: 1800129383
Assignment Date	: 17/03/2020	Excess	: S\$0.00
Date of Inspection	: 17/03/2020	Est. Duration of Repair	: 6 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,112.00 (inclusive supp)
Revised Amount	:S\$	6,788.00 (inclusive supp & labour)
Check Items (Estimated)	:S\$	850.00
Total	:S\$	7,638.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	96,000.00
COE / PARF Rebate	:S\$	45,702.00
Salvage Value	:S\$	
Margin for Repair	:S\$	50,298.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Labour no. 8 rear lid amount \$ 550.00. Supplementary amount is \$ 250.00.