



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SMG 8662 X
HONDA FIT

Not Ahd
per
2/58
STY.
19/3/20

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	REAR WINDSCREEN MOULDING	1	
2	REAR TAILGATE	1	
3	REAR TAILGATE WIPER ARM	1	
4	REAR TAILGATE WIPER MOTOR	1	
5	REAR TAILGATE WIPER MOTOR COVER	1	
6	REAR TAILGATE CHROME HANDLE	1	
7	REAR TAILGATE CHROME HANDLE LOGO	1	
8	REAR TAILGATE CHROME HANDLE LICENSE PLATE LAMP L+R	2	
9	REAR TAILGATE OPENER	1	
10	REAR TAILGATE LOCK	1	
11	REAR TAILGATE INNER TRIM TOP	1	
12	REAR TAILGATE INNER TRIM BTM	1	
13	REAR TAILGATE WEATHERSTRIP	1	
14	REAR TAILGATE LAMP L+R	2	
15	REAR TAILLAMP	2	
16	REAR TAILLAMP PANEL	1	
17	REAR BUMPER	1	
18	REAR BUMPER RETAINER L+R	2	
19	REAR BUMPER REFLECTOR L+R	2	
20	REAR BUMPER BRACKET L+R	2	
21	REAR BUMPER REINFORCEMENT BAR	1	
22	REAR BUMPER SPONGE	1	
23	REAR FENDER L+R	2	
24	REAR FENDER COWLING L+R	2	
25	REAR FENDER INNER TRIM BTM L+R	2	
26	REAR FENDER INNER TRIM TOP L+R	2	
27	REAR END PANEL	1	
28	REAR END PANEL TOP GARNISH	1	
29	REAR FLOOR PANEL	1	
30	REAR FLOOR PANEL TOP BOARD	1	
31	REAR BATTERY	1	
32	REAR BATTERY COVER	1	
33	REAR BATTERY CASING	1	
34	REAR BATTERY MOUNTING	1	
35	REAR EXHAUST PIPE	1	
36	REAR EXHAUST MOUNTING	1	
37	REAR EXHAUST GASKET	1	
38	REAR EXHAUST HEAT SHIELD	1	

		SUBTOTAL	\$ -
		LESS 20%	\$ -
		PARTS TOTAL	\$ -
SPECIAL NETT		QTY	PRICE
1	REAR NUMBER PLATE	1	\$ 120.00
2	REVERSE SENSOR	2	\$ 300.00
3	REVERSE CAM	1	\$ 1,200.00
4	REAR END PANEL SEALANT	1	\$ 120.00
5	SPARE WHEEL PANEL SEALANT	1	\$ 120.00
6	REAR BUMPER CLIPS	10	\$ 120.00
7	REAR FENDER COWLING CLIPS	10	\$ 120.00
8	REAR FENDER INNER TRIM CLIPS	10	\$ 120.00
9	BOOTLID INNER TRIM CLIPS	10	\$ 120.00
10	REAR END PANEL TOP GARNISH CLIPS	10	\$ 120.00
		SPECIAL NETT TOTAL	\$ 2,460.00
LABOUR		QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN	1	\$ 2,500.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1	\$ 2,500.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	1	\$ 120.00
4	TO RNR REAR WINDSCREEN	1	\$ 400.00
5	TO RNR REAR BOOT MECHANISM	1	\$ 120.00
6	TO RNR REAR LUGGAGE COMPARTMENT	1	\$ 400.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION.	1	\$ 300.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	1	\$ 250.00
9	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION	1	\$ 250.00
10	TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.	1	\$ 800.00
11	TO DO WATER LEAK TEST .	1	\$ 120.00
13	TO RNR FUEL TANK TO ASSIST WORK LOAD	1	\$ 120.00
14	TO RNR BATTERY AND PERFORM SAFETY TEST	1	\$ 2,500.00
		LABOUR TOTAL	\$10,380.00
		GRAND TOTAL COST	\$12,840.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: