

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 02 Apr 2020

Preliminary Advice

Vehicle No	: GBK1285G	Accident Date	: 16/03/2020
Make	: NISSAN NV200	Policy No.	: DMCVSNW00002211900
Assignment Date	: 02/04/2020	Excess	: S\$350.00
Date of Inspection	: 20/03/2020	Est. Duration of Repair	: 0.00
Inspection At	: TAN CHONG MOTOR SALES PTE LTD (HQ) 911 BUKIT TIMAH ROAD SINGAPORE 589623		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	43,000.00
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	TOTAL LOSS
Total	:S\$	TOTAL LOSS
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	57,000.00
COE / PARF Rebate	:S\$	22,701.00
Salvage Value	:S\$	
Margin for Repair	:S\$	34,299.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :