

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel: (65) 6272 3892
 Fax: (65) 6270 8314

Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

17/03/2020

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Page # :- 1

Veh # :- SJV7953U

Veh Model :- HONDA FIT

Estimate# :- CK420538

Claim # :-

ACC. Date :- 16/03/20

Terms :- C.O.D Days

Remarks :-

Attention :- XA017

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	TAILGATE / DO	1	PC 771.50	771.50 ✓
2.	TAILGATE GLASS / DR	1	PC 800.00	800.00 ✓
3.	TAILGATE GLASS MOULDING / MC	1	PC 73.00	73.00 ✓
4.	TAILGATE GLASS SEALANT / MC	1	PC 40.00	40.00 ✓
5.	TAILGATE GARNISH / DR	1	PC 119.20	119.20 ✓
6.	TAILGATE LOGO / MC	1	PC 25.00	25.00 ✓
7.	TAILGATE EMBLEM - FIT / MC	1	PC 35.00	35.00 ✓
8.	TAILGATE LOCK / DT	1	PC 189.50	189.50 ✓
9.	TAILGATE LOCK STICKER / DT	1	PC 27.50	27.50 ✓
10.	TAILGATE WEATHERSTRIP / ✓ CRU	1	PC 92.30	92.30 ✓
11.	TAILGATE HINGE TOP RH & LH / DT	2	PCS 31.00	62.00 ✓
12.	TAILGATE INNER TRIM - BOTTOM / CRV	1	PC 100.70	100.70 ✓
13.	TAILGATE DAMPER RH & LH / ✓ BT	2	PCS 136.70	273.40 ✓
14.	TAILGATE WIPER MOTOR / ✓ Jammed	1	PC 238.00	238.00 ✓
15.	TAILGATE WIPER ARM / MIS	1	PC 45.00	45.00 ✓
16.	TAILGATE WIPER BLADE / MIS	1	PC 48.00	48.00 ✓
17.	TAILGATE WIPER ARM COVER / MIS	1	PC 12.00	12.00 ✓
18.	REAR FENDER RH & LH / DO	2	PCS 652.40	1,304.80 ✓
19.	THIRD BRAKE LIGHT ASSY / CRV	1	PC 180.00	180.00 ✓
20.	REAR FENDER INNER TRIM BOTTOM RH & LH / CRV	2	PCS 250.00	500.00 ✓
21.	REAR FENDER COWLING RH & LH / X NN	2	PCS 40.40	80.80 X
22.	REAR FENDER AIR DUCT RH & LH / ✓ DEF	2	PCS 26.00	52.00 ✓
23.	REAR QUARTER GLASS SEALANT RH & LH / MC	2	PCS 40.00	80.00 ✓
24.	REAR QUARTER GLASS INNER TRIM RH & LH / CRV	2	PCS 79.80	159.60 ✓
25.	TAILLAMP ASSY RH & LH / DR	2	PCS 206.50	413.00 ✓
26.	TAILLAMP PANEL RH & LH / DO	2	PCS 133.50	267.00 ✓
27.	REAR END PANEL / DO	1	PC 765.50	765.50 ✓
28.	REAR END PANEL TOP COVER / CRV	1	PC 60.80	60.80 ✓
29.	REAR BUMPER / DR	1	PC 497.40	497.40 ✓
30.	REAR BUMPER BRACKET RH & LH / X NN	2	PCS 38.50	77.00 X
31.	REAR BUMPER RETAINER RH & LH / DR	2	PCS 16.80	33.60 ✓
32.	REAR BUMPER CLIPS / MC	10	PCS 3.90	39.00 ✓
33.	SPARE TYRE COVER / ✓ DEF	1	PC 190.70	190.70 ✓
34.	SPARE WHEEL PANEL / X R	1	PC 737.00	737.00 X
35.	REAR CHASSIS MEMBER LH / X R	1	PC 180.00	180.00 X
36.	REAR AXLE - CHECK / X NN	1	PC	
37.	REAR SHOCK ABSORBER RH & LH / X NN	2	PCS 190.70	381.40 X
38.	REAR DOOR LOCK RH - CHECK / X NN	1	PC	
39.	ROOF LINING - CHECK / ✓ DEF	1	PC	
40.	ROOF PANEL (REPAIR) / X R	1	PC	
41.	REAR DOOR RH & LH (REPAIR) / X R	2	PCS	
LIST TOTAL S\$				8,951.70
20% DISCOUNT S\$				-1,790.34
8194.50				
-20%				
6555.60				
				7,161.36

SPECIAL NET ITEMS :

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel: (65) 6272 3892
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

17/03/2020

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Page # :- 1 137851

Veh # :- SJV7953U

Veh Model :- HONDA FIT

Estimate# :- CK420538

Claim # :-

ACC. Date :- 16/03/20

Terms :- C.O.D Days

Remarks :-

Attention :- XA017

No.	Description	Qty	U.Price	Amounts S\$
4.	REAR EXHAUST EXTENSION PIPE X NN	1 PC	150.00	150.00 X
	SPECIAL NET TOTAL S\$	240		640.00
	LABOUR : TO CUT/WELD REAR FENDER RH & LH, TAILLAMP PANELS, REAR END PANEL, SPARE WHEEL PANEL, REAR CHASSIS MEMBER LH. KNOCK AND STRAIGHTEN ROOF PANEL, REAR FENDER INNER PANELS, REAR CHASSIS MEMBER RH. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION.		1800	2,400.00
	SPRAY PAINT TAILGATE, ROOF PANEL, REAR FENDER RH & LH, REAR FENDER INNER PANEL RH & LH, SPARE WHEEL PANEL, REAR CHASSIS MEMBERS RH & LH, REAR DOORS RH & LH, REAR BUMPER		1400	1,800.00
	REMOVE & REPLACE TAILGATE GLASS AND CHECK WATER LEAKAGE			120.00 /
	REMOVE & REPLACE TAILGATE INNER TRIM, MECHANISM AND CHECK LOCKING SYSTEM			50.00 /
	REMOVE & REPLACE REAR QUARTER GLASS AND CHECK WATER LEAKAGE		150	200.00
	REMOVE & REFIT PETROL TANK, PIPE, HOSE		50	80.00
	REMOVE & REAR DOOR INNER TRIM, MECHANISM AND LOCKING SYSTEM			40.00 /
	REMOVE & REFIT ROOF LINING, UPHOLSTERY, SIDE GARNISH, REAR SEAT ASSY, REAR FLOOR CARPET, INNER TRIMS, COVERING		80	180.00
	REMOVE & REINSTALL EXHAUST SILENCER, HEAT COVER, MOUNTINGS			✓ 80.00 X
	REMOVE & REINSTALL REVERSE SENSOR AND CHECK FUNCTION		30	50.00
	REMOVE & REINSTALL REAR AXLE, SUSPENSIONS			250.00 X
	TO APPLY SEAL ON WELDING JOINTS			180.00 X
	CHECK CHASSIS WHEEL ALIGNMENT ON LASER LOCK MACHINE		200 ✓	280.00 X

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

17/03/2020

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Page # :- 1 137851

Veh # :- SJV7953U

Veh Model :- HONDA FIT

Estimate# :- CK420538

Claim # :-

ACC. Date :- 16/03/20

Terms :- C.O.D Days

Remarks :-

Attention :- XA017

No.	Description	Qty	U.Price	Amounts S\$
	COMPUTER WHEEL ALIGNMENT			60.00
	LABOUR TOTAL S\$			5,930.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 13,731.36

GST @ 7 % 961.20

AMOUNT DUE S\$ 14,692.56

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Steve (LKK) wkl R
20/3/20, 11.30am
14 dys
L/S
My A. My

P - 6555.60

N - 240

L - 4050

10,845.60

L/S - 8,676.48
= 8700

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: