



AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
 Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre
 Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

Car Plate No. GBE 4655J

Date of Accident : 17-03-2020

Model Toyota Dyna

Time of Accident : 17:15

Venue : Sembawang Rd
 Chong Pang

No	Qty	Parts Description	Estimated Parts Price
----	-----	-------------------	-----------------------

Supplementary Items

87.555w

1 1 Door outer wheather moulding 175.10

\$ 210.00 506w

2 1 Front bumper assy

\$ 952.00 X

3 1 RH head lamp

\$ 872.90 ✓

\$ 2,034.90

258

Special Nett Items

1 RH door decal (lower)

NEC

\$ 40.00 25/2

\$ 40.00

Total \$ 2,074.90