Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4

Singapore 038986

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

From: LKK Auto Consultants Pte Ltd

Attn: Eileen Bay

29 Apr 2020 Date:

Preliminary Advice

Vehicle No : SLJ6942Y Accident Date : 21/03/2020

Make : TOYOTA WISH Policy No. : PNPV2019-00017937

Assignment Date : 24/03/2020 **Excess** : S\$750.00 Date of Inspection : 24/03/2020 Est. Duration of Repair : 10.00

Inspection At : PROGRESSIVE CAR CARE PTE LTD (HQ)

BLK 3022A UBI ROAD 1, #01-45/46

SINGAPORE 408716

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident. The chassis frame affected due to collision.

Repairer's Estimate (Gross)	:S\$	(ESTIMATE \$10,108.00 + 14,038.00 SUPP 1 \$3,810.00 + SUPP 2 \$120.00)
Revised Amount	:S\$	(INCLUSIVE OF 11,172.00 SUPPLEMENTARY & CHECK ITEMS)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	11,172.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	68,000.00
COE / PARF Rebate	:S\$	50,658.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,342.00

Remarks

(X)	The vehicle is repairable at our adjusted amount.	We have also confirmed	≀excess and policy coverage	. Kindly let us
	have your authorisation.			

·) The	e vehicle is	uneconomical	to be	repaired.	vou are	advised	to ir	vite	tender	for th	ie wre	ck

(X) Other comments: KINDLY APPROVE ON SUPPLEMENTARY & CHECK ITEMS.