



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS/LPC20004430/Ktd3s2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 16-04-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 4967D	Veh. Inspected	SLU 9931B
Policy No.		Coverage (\$)	0.00
Claim No.	19/20/20/VC06/023224	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	24/03/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA CHR (A)	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZYX102082805	Colour	METALLIC GREY
Odometer	125751	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R17	YOKOHAMA	7 mm
L/H Front Tyre	215/60 R17	YOKOHAMA	7 mm
R/H Rear Tyre	215/60 R17	YOKOHAMA	7 mm
L/H Rear Tyre	215/60 R17	YOKOHAMA	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR BODY. DAMGES SEE DETAILS.
--

5. General Information

Accident Date	20/03/2020	Inspection Date	24/03/2020
Survey held at	LIAN HER MOTORS BLK 5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405 SINGAPORE 569541.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------