

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SLM 1710S

Date : 23.03.2020

Vehicle Model : HONDA VEZEL HYBRID

Chassis : RU31215129

Accident Date : 22.03.2020

TP Ins. **AIG**

Original Reg Date : 22.03.2017

SUPPLEMENTARY

1	1 pc	Side Skirts <i>dis ✓</i>	430	571.50
2	1 set	Side Skirt Clip <i>rec ✓</i>	30	40.00

460

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autoteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SLM 1710S
Vehicle Model : HONDA VEZEL HYBRID
Accident Date : 22.03.2020
Original Reg Date : 22.03.2017

Date : 23.03.2020
Chassis : RU31215129
TP Ins. **AIG**

ESTIMATE

1	1 pc	Front Door LH		980.00	bt✓
2	1 pc	Front Door Outer Moulding LH		89.00	x nn
3	1 pc	Front Door Black Sticker LH		49.20	nei✓
4	2 pcs	Front Door Hinges	56.00	224.00	Rn
5	1 pc	Front Door Checker		62.00	x Rn
6	1 pc	Front Door Inner Lock		269.20	? bt✓
7	1 pc	Front Door Lock Catch		46.00	x nn
8	3 pcs	Front Door Weatherstrips - photo	35.00	105.00	cut
9	1 pc	Front Door Regulator Motor and Gear		452.80	? bt✓
10	1 pc	Front Door Channel		96.50	x nn
11	1 pc	Front Door Channel Seal		112.00	x nn
12	1 pc	Front Door Inner Trim	560	752.00	cut✓
13	1 pc	Front Door Inner Trim Clips		40.00	nei✓ 20.
14	1 pc	Rear Door LH		960.00	bt✓
15	1 pc	Rear Door Outer Moulding		89.00	x nn
16	1 pc	Rear Door Black Sticker		49.20	nei✓
17	1 pc	Rear Door Transparent Sticker		39.00	nei✓
18	2 pcs	Rear Door Hinges top-Xnn	56.00	112.00	bottom/bt✓
19	1 pc	Rear Door Checker		62.00	x nn
20	6 pcs	Rear Door Weatherstrips - photo	35.00	105 140.00	nei✓

LH centre pillar 8563.20. Rn

4,728.90

Less 20% 945.78

3,783.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

3645.40
supp - 460
4105.40
20% - 3284.32

C/D

3,783.12

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No. : SLM 1710S

B/F

3,783.12

Special Nett

1	1 set	Door Side Protector	180.00
---	-------	---------------------	--------

2 → Chassis No. sticker
Labour charge

280
+50 100

Panel Beating	1,300.00	900.
Spray painting	1,300.00	1000.
Check Wiring	50.00	30.
Anti rust	120.00	100.00
Remove and install both front and both rear door parts.	180.00	120.
Remove and install carpet and seat.	150.00	60.
To reset , reprogram and eraser fault code.	220.00	120.

7,283.12

Less 20% 1,456.62

Lump sum 5,826.50

2300

Tanfilin 974957495 3284.32
WP' 24/3/20 280

Lumpsum 2300

Resumy after repair 5864.32

Tanfilin @ 11 hours. 07 days 20% = 4700

7 days

1	980.00	571.50	180.00	900.00
2			100.00	1,000.00
3	49.20		30.00	
4			70.00	
5			120.00	
6	269.20		60.00	
7			120.00	
8	105.00			
9	452.80			
10				
11				
12	752.00			
13	20.00			
14	960.00			
15				
16	49.20			
17	39.00			
18	112.00			
19				
20	105.00			
21	563.20			

Total List Price	\$	5,028.10
Discount		20%
List Price	\$	4,022.48
Total Nett Price	\$	280.00
Discount		20%
Nett Price	\$	224.00
Total Special Nett	\$	280.00
Total Labour	\$	2,300.00
Grand Total	\$	6,826.48
Discount 20%		20%
Lump Sum	\$	5,461.18

Columns	Serial No.
A	List Price
B	Supplementary
C	Special Nett
D	Labour
E	

Vehicle No. DOA
SLM 1710S 22.03.2020

Model
HONDA VEZEL