

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721

TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

Not Authorise
11 Day @ ?
Permy After Paint
7 days

GOH HANLI JASON

c/o 46 Lenton Plain

Singapore 786548

Date: 23/3/2020

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: HONDA SHUTTLE / SGL 8842 M	
1 pc	front door (right)	1,167.00 ✓
1 pc	front door handle	215.40 X
1 pc	front door handle cover	47.20 X
1 pc	front door lock cylinder	215.00 X
1 pc	front door lock	178.60 ✓
1 pc	front door lock catch	89.30 A
1 pc	front door window regulator	576.10 ✓
1 pc	rear door window regulator motor	336.70 X
2 pcs	rear door hinge @ 176.30	352.60 X
1 pc	rear door window regulator	578.50 ✓
1 pc	rear door window regulator motor	336.70 ✓
1 pc	front door weatherstrip	239.10 X
1 pc	rear door weatherstrip	298.80 ✓
1 pc	front wheel bearing	345.10 ✓
1 pc	front wheel hub	415.30 ✓
1 pc	front knuckle arm	511.30 ✓
1 pc	front shock absorber	478.80 X
1 pc	rear wheel bearing	514.30 ✓
1 pc	front door frame sticker (1)	131.30 ✓
1 pc	front door frame sticker (2)	144.90 ✓
1 pc	rear door frame sticker	135.80 ✓
1 pc	"B" pillar outer panel	915.30 X
1 pc	rear bumper	756.50 X
1 pc	rear bumper side retainer	77.60 X
1 pc	side rocker panel skirt	10.70 ✓
	sub-total	9,067.90
	less 20%	1,813.58
	sub-total	7,254.32

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

	balance brought forward.			7,254.32
2 pcs	alloy rim	s.nett @	650.00	<i>500m</i> <i>pu</i> 1,300.00
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.			<i>700</i> 1,200.00
	To check wiring system.			<i>200</i> 50.00
	To apply rust proofing on affected areas.			<i>600</i> 120.00
	To apply waterproof sealant on affected areas.			<i>nn</i> <i>600</i> 120.00 <i>1</i>
	To apply putty & spray painting on affected areas.			<i>1,200.00</i> <i>1000</i>
	To remove carpet, trimming and seats to enable repair.			<i>nn</i> 120.00 <i>1</i>
	To transfer 2 doors' accessories.			120.00 <i>L</i>
	To replace 2 alloy rims & perform wheel balancing.			<i>400</i> 80.00
	To machine press wheel bearing.			<i>7</i> 60.00
	To perform 4 wheels computerised alignment.			<i>600</i> 85.00
	Towing charges.			<i>400</i> 50.00 <i>1</i>
	To benchmount & align frame.			<i>nn</i> 400.00 <i>X</i>
			total	12,159.32