

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

GOH HANLI JASON
c/o 46 Lentor Plain
Singapore 786548

Date: 23/3/2020

QUANTITY	PARTICULARS	AMOUNT (\$)
	<u>RE: HONDA SHUTTLE / SGL 8842 M</u>	
1 pc	front door (right)	1,167.00
1 pc	front door handle	215.40
1 pc	front door handle cover	47.20
1 pc	front door lock cylinder	215.00
1 pc	front door lock	178.60
1 pc	front door lock catch	89.30
1 pc	front door window regulator	576.10
1 pc	rear door window regulator motor	336.70
2 pcs	rear door hinge @ 176.30	352.60
1 pc	rear door window regulator	578.50
1 pc	rear door window regulator motor	336.70
1 pc	front door weatherstrip	239.10
1 pc	rear door weatherstrip	298.80
1 pc	front wheel bearing	345.10
1 pc	front wheel hub	415.30
1 pc	front knuckle arm	511.30
1 pc	front shock absorber	478.80
1 pc	rear wheel bearing	514.30
1 pc	front door frame sticker (1)	131.30
1 pc	front door frame sticker (2)	144.90
1 pc	rear door frame sticker	135.80
1 pc	"B" pillar outer panel	915.30
1 pc	rear bumper	756.50
1 pc	rear bumper side retainer	77.60
1 pc	side rocker panel skirt	10.70
	sub-total	9,067.90
	less 20%	1,813.58
	sub-total	7,254.32

	balance brought forward.			7,254.32
2 pcs	alloy rim	s.nett @	650.00	1,300.00
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.			1,200.00
	To check wiring system.			50.00
	To apply rust proofing on affected areas.			120.00
	To apply waterproof sealant on affected areas.			120.00
	To apply putty & spray painting on affected areas.			1,200.00
	To remove carpet, trimming and seats to enable repair.			120.00
	To transfer 2 doors' accessories.			120.00
	To replace 2 alloy rims & perform wheel balancing.			80.00
	To machine press wheel bearing.			60.00
	To perform 4 wheels computerised alignment.			85.00
	Towing charges.			50.00
	To benchmount & align frame.			400.00
			total	12,159.32