



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 24/03/2020

User ID : BoonChewTay

Section A - Accident Details

Registration Number	TIB1241Y
Case Reference Number	BUS/03/20/1040
Registration Date	14/11/2003
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MERCEDES C405G
Name of Driver	Chen Rihui
Type of Accident	Side Swipe
Accident Date and Time	20/3/2020 4:29 PM
Accident Reported Date and Time	20/3/2020 5:45 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	TIB1241Y-RIGHT REAR PORTION SKC2977Y (TP) INSURED WITH AIG
Prepared Date and Time	24/3/2020 10:21 AM
Chassis Number	WEB61232321099676
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$354.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,149.00	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	24/03/2020 10:25 AM	
Signature		x
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	