

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 19 Jun 2020

Preliminary Advice

Insured Vehicle No	: PC7956R		
TP Vehicle No	: SGS5755P	Accident Date	: 24/03/2020
Make	: TOYOTA CAMRY	Assignment Date	: 26/03/2020
Date of Inspection	: 26/03/2020	Est. Duration of Repair	: 12 days
Inspection At	: Borneo Motors (S) Pte Ltd (Ubi) 17 Ubi Road 4 Singapore 408611		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	34,464.25
Revised Amount	:S\$	20,890.45
Check Items (Estimated)	:S\$	0.00
Total	:S\$	20,890.45
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP