# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd. 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

From: LKK Auto Consultants Pte Ltd

Attn: Date: 27 Mar 2020

## **Preliminary Advice**

Insured Vehicle No : YP1148X

TP Vehicle No : GBG1005U Accident Date : 23/03/2020

Make : NISSAN NV200 Assignment Date : 26/03/2020

Date of Inspection : 26/03/2020 Est. Duration of Repair : 7 days

Inspection At : YEE AUTO PTE LTD (HQ)

160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY

SINGAPORE 575722

## Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 21,217.50 |
|-----------------------------|------|-----------|
| Revised Amount              | :S\$ | 7,212.17  |
| Check Items (Estimated)     | :S\$ | 4,021.66  |
| Total                       | :S\$ | 11,233.83 |

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :\$\$
Pre-Accident Value :\$\$
COE / PARF Rebate :\$\$
Salvage Value :\$\$
Margin for Repair :\$\$

### Remarks

| ( | ) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. |
|---|---|--|
|   |   | Kindly let us have your authorisation.   |
|   |   |  |

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: TP: WP