

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pang Xiu Shi

Date: 30 Mar 2020

Preliminary Advice

Vehicle No	: SGB2525X	Accident Date	: 25/03/2020
Make	: VOLKSWAGEN GOLF	Policy No.	: 29121145AVW
Assignment Date	: 27/03/2020	Excess	: S\$500.00
Date of Inspection	: 27/03/2020	Est. Duration of Repair	: 11 days
Inspection At	: Volkswagen Centre Singapore (Tuas) 17 TUAS AVENUE Singapore 639176		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s & o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	26,427.30
Revised Amount	:S\$	15,829.47
Check Items (Estimated)	:S\$	2,316.12
Total	:S\$	18,145.59

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	88,000.00
COE / PARF Rebate	:S\$	38,605.00
Salvage Value	:S\$	
Margin for Repair	:S\$	49,395.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.