

EURO SUCCESS SERV PTE LTD

Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231

FAX: 67411019

H/P: 98289277 (AH HUAT)

Vehicle No: SKC7201U

Model: MITSUBISHI LANCER GLX

Denise

not Authorized
Leak

L/S @ 4000/
12 days

Take place After

QTY	List Items	Price \$
1	REAR BOOT LID	Buc 595.00 ✓
1	REAR BOOT SPOILER	N 890.00 X
1	REAR BOOT THIRD BRAKE LIGHT	Che 225.00 ✓
2	REAR BOOT DAMPERS @121	NS 242.00 X
1	REAR BOOT LOGO	nu 42.00 ✓
1	REAR BOOT EMBLEM GLX	nu 28.00 ✓
1	REAR BOOT EMBLEM LANCER	nu 24.00 ✓
1	REAR BOOT NUMBER PLATE GARNISH	N 197.00 X
1	REAR BOOT WEATHERSTRIP	twi 139.00 ✓
2	REAR BOOT HINGE @ 125	but 250.00 ✓
1	REAR BOOT INNER TRIM	1m 158.00 X
1	REAR BOOT INNER LOCK	twi 89.00 ✓
1	REAR BOOT LOCK STRIKER	11 28.00 X
1	REAR BOOT SPEAKER PANEL	11 950.00 X
2	REAR BOOT SPEAKER @ 300	11 600.00 X
1	REAR L/H DOOR INNER LOCK	11 380.00 X
2	REAR TAILLAMPS @414	bro 828.00 ✓
2	REAR TAILLAMP PANEL @85	N 170.00 X
1	REAR BUMPER	DLS 662.00 ✓
1	REAR BUMPER LOWER SPOILER	To.n 653.00 ✓
1	REAR BUMPER BREAM Beam 171	but 186.00 ✓
2	REAR BUMPER SIDE RETAINERS @85	but 170.00 ✓
1	REAR BUMPER REINFORCEMENT	Reptd 189.00 X
1	REAR BUMPER TOWING COVER	NS 18.00 X
1	REAR END PANEL 416	Body 435.00 ✓
1	REAR END PANEL INNER GARNISH	twi 132.00 ✓
1 SET	REAR END PANEL INNER GARNISH CLIPS	11 18.00 X
1	REAR SPARE TYRE PANEL	N 970.00 X
1	REAR FLOOR PANEL	Reptd 472.00 X
1	REAR FLOOR BOARD panel top board	To.n 290.00 ✓
2	REAR FENDER INNER TRIMS @ 286	To.n 572.00 ✓
1	REAR EXHAUST SILENCER	N 445.00 X
2	REAR EXHAUST MOUNTING @ 48	11 96.00 X
2	REAR FENDER L-R @865	N 1730.00 X
2	REAR FENDER INNER PANEL L-R @950	11 1900.00 X
2	REAR WHEEL BEARING L-R @ 320	11 640.00 X
2	REAR SHOCK ABSORBER L-R @426	11 852.00 X
2	REAR KNUCKLE ARM L-R @ 520	11 1040.00 X
2	REAR KNUCKLE L-R @ 475	11 950.00 X
2	REAR LOWER ARM L-R @ 382	11 764.00 X
2	REAR TRIM ARM L-R @627	11 1254.00 X
1	REAR CROSS MEMBER	11 950.00 X

2 REAR CHASSIS FRAME L-20-850
 1 REAR FUEL HOSE
 1 REAR FUEL CAP
 2 pcs REAR WINDSCREEN MOULDING
 2 REAR SEAT BELT @530

1700.00 X
 17 66.00 X
 17 38.00 X
 17 220.00
 17 1060.00 X

TOTAL \$24,307.00
 LESS 10% \$2,430.70
 TOTAL \$21,876.30

Special Nett Items

1 SET REAR BOOT INNER TRIM CLIPS
 1 SET REAR BUMPER CLIP
 1 SET REAR NUMBER PLATE WITH HOLDER
 1 SET REAR REVERSE SENSOR
 1 REAR WINDSCREEN SEALANT

17 45.00 X
 20 45.00 40
 30 70.00 40
 70 350.00 200
 17 80.00 X

\$590.00

Labour Charges

TOWING CHARGES
 TO PROVIDE WHEEL ALIGNMENT
 TO REMOVE AND REFIX REAR FUEL TANK
 TO REALIGN REAR CHASSIS FRAME
 TO CHECK REAR ELECTRICAL WIRING
 TO REMOVE, REFIX REAR WINDSCREEN
 TO REMOVE, REFIX REAR SEAT, INTERIOR TRIMS TO ASSIST REPAIR
 TO REMOVE, REFIX REAR UNDERCARRIAGE
 TO REMOVE REAR SEAT, ROOF AND FLOORBOARD TO ASSIST REPAIR
 TO RESPRAY UNDERCOATING
 TO REMOVE REPLACE REAR CAR ARMS
 TO RESPRAY PAINTING AND ETC
 PANEL BEATING, CUT, WELD REMOVE AND REPLACING ABOVE PARTS

120.00 50
 17 250.00 X
 300.00 60
 17 400.00 X
 250.00 30
 17 180.00 X
 200.00 80
 17 650.00 X
 17 450.00 X
 650.00 80
 17 400.00 X
 2000.00 1100
 3000.00 1200

\$8,850.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$31,316.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P-5206
 102
 P-4955-4
 S.W-280.00
 L-2600.00
 7835.4
 6268