

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AIG	DATE	: 25/03/2020
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SJQ79R		
MODEL	: LEXUS GX350		
CHASSIS NO			
ACCIDENT DETAILS		DATE	: 24-Mar-20
		TIME	: 09:10HRS
THIRD PARTY REQUESTOR / COI.	JACK LI		

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>del</i>	1	\$ 920.00	\$ 920.00
2	FRONT BUMPER SIDE RETAINER <i>re</i>	2	\$ 69.36	\$ 138.72
3	FRONT BUMPER REINFORCEMENT <i>re</i>	1	\$ 680.00	\$ 680.00
4	FRONT BUMPER REINFORCEMENT SPONGE <i>can</i>	1	\$ 230.00	\$ 230.00
5	FRONT BUMPER LOWER GRILLE <i>can</i>	1	\$ 210.00	\$ 210.00
6	FRONT BUMPER REVERSE SENSOR <i>del</i>	1	\$ 320.00	\$ 320.00
7	FRONT BUMPER INNER AIR DUCT <i>re</i>	1	\$ 290.00	\$ 290.00
8	FRONT BUMPER NUMBER PLATE HOLDER <i>del</i>	1	\$ 190.00	\$ 190.00
9	CENTRE GRILLE <i>lt</i>	1	\$ 988.70	\$ 988.70
10	CENTRE GRILLE CHROME <i>lt</i>	1	\$ 360.00	\$ 360.00
11	CENTRE GRILLE LOGO <i>re</i>	1	\$ 190.00	\$ 190.00
12	HEADLAMP RH <i>can</i>	1	\$ 3,885.90	\$ 3,885.90
13	HEADLAMP LOWER BRACKET RH <i>re</i>	1	\$ 140.00	\$ 140.00

TOTAL PRICE \$ 8,543.32

LESS 10% \$ 854.33

SUB TOTAL PRICE \$ 7,688.99

6924.62

6232.15

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>on L2</i>	1	\$ 50.00	\$ 50.00 ✓
2	FRONT BUMPER CLIPS(SET) <i>m</i>	1	\$ 20.00	\$ 20.00 ✓
3	CENTRE GRILLE CLIPS(SET) <i>m</i>	1	\$ 20.00	\$ 20.00 ✓

90

TOTAL \$ 40.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 600.00	<i>300</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 600.00	<i>250</i>	
3	TUFF COAT	\$ 180.00	<i>x</i>	
4	WIRING CHECK	\$ 100.00	<i>30</i>	
5	TO REMOVE AND REFIX FRONT REVERSE SENSOR	\$ 120.00	<i>50</i>	
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 220.00	<i>x</i>	

TOTAL

\$1,820.00

630

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,728.99
 TOTAL LABOUR COST : \$ 1,820.00
 TOTAL REPAIR COST : \$ 9,548.99

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Admin Lj
r/s 25/03/20
03 Days.

total: 6952.15
L/S: 5512. ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: