

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 33977

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0331/2020/NS
Date : 26-Mar-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

*9 days exclude 1 Sunday -Added job
jb 25 Jun 20*

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Roro Dewi Mashita Binti Mamat
Address : 15 Maida Vale
Singapore 798690
Telephone : HP +65 90287743
Type of Claim : Own Damage Claim
Policy No. : 2100473271-03
Vehicle No : **SLD 8595 J**
Model Code : Audi Q5 2.0 TFSI qu
Model / Year : Jun-16
Engine No : CNC 168468
Chassis No : WAUZZZ8R5GA141796
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 24-Mar-20
Place of Accident : 15 Maida Vale

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLD 8595 J

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer lhs front door and lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$	560.00	\$ 560.00
2	To remove and reinstall lhs rear back rest, ABCD pillar trims, sill trims, carpets, electronic components and fuse trays.	S/N \$	1,400.00	
3	To dismantle and renew lhs front door and lhs rear door. To cut out and weld lhs sill panel. Re-organise crash management components. Reinstall all parts removed.	\$	4,800.00	\$ 1,500.00
4	To respray lhs front door, lhs rear door, door covers, lhs sill panel and door entrances. To carry out stone chip treatment and joint sealer works.	\$	4,600.00	\$ 2,050.00
5	To renew lhs rear rim and carry out wheel alignment.	S/N \$	280.00	\$ 280.00
5a	Added labour charge - see attached	S/N \$	480.00	\$ 480.00
6	Added labour charges - see attached	\$	3,000.00	\$ 2,100.00
7	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 15,312.00	\$ 7,162.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLD 8595 J

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT DOOR - LH	\$ 2,972.00	\$ 2,377.60
2	FRONT DOOR ATTACHMENT PARTS	\$ 121.00	
3	FRONT DOOR OUTER SEAL - LH	NEC \$ 193.00	\$ 154.40
4	BONDING AGENT	NEC \$ 46.00	\$ 36.72
5	CLEANING SOLUTION	NEC \$ 64.00	\$ 51.20
6	FRONT DOOR CATCH	\$ 137.00	
7	FRONT DOOR COVER - LH	\$ 482.00	\$ 385.20
8	REAR DOOR - LH	\$ 2,972.00	\$ 2,377.60
9	REAR DOOR OUTER SEAL - LH	NEC \$ 193.00	\$ 154.40
10	BONDING AGENT	NEC \$ 46.00	\$ 36.72
11	CLEANING SOLUTION	NEC \$ 64.00	\$ 51.20
12	STONE CHIP PROTECTION FILM - LH INNER	\$ 73.00	\$ 58.40
13	REAR DOOR ATTACHMENT PARTS	\$ 117.00	
14	REAR DOOR CATCH	\$ 137.00	
15	REAR DOOR HINGE - LH UPPER / LOWER	2 \$ 285.00	
16	SILL PANEL SEAL - LH	\$ 209.00	\$ 167.20
17	INNER DOOR SEAL	\$ 193.00	
18	REAR DOOR COVER - LH	\$ 385.00	\$ 308.00
19	SILL PANEL - LH	\$ 2,031.00	
20	SILL TRIM STRIP - LH REAR	\$ 135.00	\$ 108.00
SUB TOTAL SPARE PARTS CHARGES		\$ 10,855.00	\$ 6,266.64

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLD 8595 J

		<u>Damage Parts & Prices</u>	
S/N	Parts Description	S/Nett	Remarks
	<i>c/f</i>		\$ 6,266.64
21	REAR ALUMINIUM RIM - LH	\$ 944.00	\$ 754.80
22	UNDERBODY TRIM - LH	\$ 315.00	\$ 252.00
23	REAR WHEEL HOUSING LINER - LH	\$ 248.00	
24	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 98.00	
25	ACRYLIC SEALANT	S/N \$ 180.00	
26	CAVITY WAX	S/N \$ 140.00	
27	STONE CHIP	S/N \$ 180.00	
28	Added parts - see attached	\$ 226.00	\$ 180.80
29	SUNDRIES	\$ 400.00	\$ 3.36
TOTAL SPARE PARTS CHARGES		\$ 13,586.00	\$ 7,457.60
TOTAL LABOUR CHARGES		\$ 15,312.00	\$ 7,162.00
GRAND TOTAL		\$ 28,898.00	\$ 14,619.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0331/2020/NS 13-May-20 Glory Tan 1 of 1 SLD 8595 J Audi Q5 2.0 TFSI qu
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Sill trim strip for front door entrance LHS	\$ 226.00	\$ 180.80
<u>Labours</u>			
1	To repair lhs sill panel and lhs B-pillar.	\$ 1,000.00	\$ 1,000.00
2	To respray lhs sill panel and lhs B-pillar.	\$ 2,000.00	\$ 1,100.00
TOTAL		\$ 3,226.00	\$ 2,280.80

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0331/2020/NS 13-May-20 Glory Tan 1 of 1 SLD 8595 J Audi Q5 2.0 TFSI qu	
Quantity	Description	Unit Price	Amount	
<u>Labours</u> 1	To remove and reinstall lhs s/n B-pillar lower trim to facilitate B-pillar repair.	480	\$	480.00
TOTAL		\$ 480.00	\$	480.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant