

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0331/2020/NS

Date

13-May-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SLD 8595 J

Model No

Audi Q5 2.0 TFSI qu

Quantity	Description	Unit Price	Amount
Parts			
1	Sill trim strip for front door entrance LHS <i>see</i>	\$ 226.00	
Labours			
1	To repair lhs sill panel and lhs B-pillar.	\$ 1,000.00	
2	To respray lhs sill panel and lhs B-pillar.	\$ 2,000.00 1100	
TOTAL		\$ 3,226.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Premium Automobiles Pte Ltd

Rahul
13/05/2020

extra 3 days

Authorised Signature

*Subject to
insurance approval*